

## NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO:

Mr. J. G. Keppler

FROM:

Indiana & Michigan Power Co.  
Bridgman, Michigan  
R. W. Jurgensen

DATE OF DOCUMENT

8/4/76

DATE RECEIVED

8/9/76

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

☐ ORIGINAL☒ UNCLASSIFIED☒ COPY

NUMBER OF COPIES RECEIVED

One signed copy

## DESCRIPTION

Ltr. trans the following:

ACKNOWLEDGED

DO NOT REMOVE

(1-P)

PLANT NAME:

Cook #1

## ENCLOSURE

Licensee Event Report (RO 50-315/76-30) on  
7/5/76 concerning an ice buildup at the bottom  
of 2 lower inlet doors while in mode 5, during  
ice condenser inlet door opening surveillance  
testing.

(2-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J..COLLINS

FOR ACTION/INFORMATION

8/10/76

R.JL

<input checked="" type="checkbox"/> BRANCH CHIEF:	Ziemann		
<input checked="" type="checkbox"/> W/3 CYS FOR ACTION			
<input checked="" type="checkbox"/> LIC. ASST.:	Diggs		
<input checked="" type="checkbox"/> W/1 CYS			
<input checked="" type="checkbox"/> ACRS/6 CYS HOLDING/SENT TO LA			

## INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE				
<input checked="" type="checkbox"/> NRC PDR				
<input checked="" type="checkbox"/> I & E (2)				
<input checked="" type="checkbox"/> MIPC				
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO				
<input checked="" type="checkbox"/> HOUSTON				
<input checked="" type="checkbox"/> NOVAK/CHECK				
<input checked="" type="checkbox"/> GRIMES				
<input checked="" type="checkbox"/> CASE				
<input checked="" type="checkbox"/> BUTLER				
<input checked="" type="checkbox"/> HANAUER				
<input checked="" type="checkbox"/> TEDESCO/MACCARY				
<input checked="" type="checkbox"/> EISENHUT				
<input checked="" type="checkbox"/> BAER				
<input checked="" type="checkbox"/> SHAO				
<input checked="" type="checkbox"/> VOLLMER/EUNCH				
<input checked="" type="checkbox"/> KREGER/J..COLLINS				

## EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> LPDR: St. Joseph, Mi/				
<input checked="" type="checkbox"/> TIC:				
<input checked="" type="checkbox"/> NSIC:				

CONTROL NUMBER

8059

529

100

Condition	10 years	12 years	14 years
1	~85%	~75%	~65%
2	~75%	~65%	~55%
3	~65%	~55%	~45%
4	~55%	~45%	~35%
5	~45%	~35%	~25%

• • •

5 10 15 20 25 30 35 40 45 50 55 60 65 70 75 80 85 90 95 100

the 1990s, the number of people in the world who are undernourished has declined from 1.1 billion to 800 million. The number of people who are malnourished has declined from 1.5 billion to 1 billion. The number of people who are obese has increased from 100 million to 300 million. The number of people who are overweight has increased from 100 million to 300 million. The number of people who are obese and overweight has increased from 100 million to 300 million. The number of people who are obese and overweight has increased from 100 million to 300 million.

10. The following are the names of the persons who have been appointed to the various committees of the Board of Directors:

11-12

4.

20

1000 1000

•

2

11

100

Regulatory


File Cy.



**INDIANA & MICHIGAN POWER COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106

August 4, 1976



Mr. J.G. Keppler, Regional Director  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2.b, the following report is submitted:

RO 50-315/76-30.


Sincerely,

For R.W. Jurgensen  
Plant Manager

/bab

cc: R.S. Hunter  
J.E. Dolan  
G.E. Lien  
R. Kilburn  
R.J. Vollen BPI  
R.C. Callen MPSC  
K.R. Baker RO: III  
P.W. Steketee, Esq.  
R. Walsh, Esq.  
G. Charnoff, Esq.  
G. Olson  
J.M. Hennigan  
PNSRC  
R.S. Keith  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

8059



# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 M I D C C 1 14 15 0 0 - 0 0 0 0 - 0 0 25 26 4 1 1 1 1 30 31 0 3 32

CONT: 01 57 58 59 60 61 0 5 0 - 0 3 1 5 68 69 0 7 0 5 7 6 74 75 0 8 0 4 7 6 80

## EVENT DESCRIPTION

02 7 8 9 WHILE IN MODE 5; DURING ICE CONDENSER INLET DOOR OPENING TORQUE SURVEILLANCE TESTING, IT  
03 7 8 9 WAS FOUND THAT THERE WAS AN ICE BUILDUP AT THE BOTTOM OF 2 LOWER INLET DOORS, BAY 3  
04 7 8 9 RIGHT HAND DOOR AND BAY 5 LEFT DOOR. THIS CONDITION CAUSED THE INITIAL OPENING FORCE TO  
05 7 8 9 BE IN EXCESS OF TECHNICAL SPECIFICATIONS PARAGRAPH 4.6.5.3.1.b 1 and 2.  
06 7 8 9 (R0-50-315/76-30)

SYSTEM CODE: 07 7 8 9 10 11 12 13 14 15 16 17 CAUSE CODE: 07 11 COMPONENT CODE: 07 12 13 14 15 16 17 PRIME COMPONENT SUPPLIER: 07 43 COMPONENT MANUFACTURER: 07 44 45 46 47 VIOLATION: 07 48

## CAUSE DESCRIPTION

08 7 8 9 SEE SUPPLEMENT.  
09 7 8 9  
10 7 8 9

FACILITY STATUS: 11 7 8 9 10 11 12 13 14 15 16 17 % POWER: 11 12 13 14 15 16 17 OTHER STATUS: 11 12 13 14 15 16 17 METHOD OF DISCOVERY: 11 44 45 46 47 48 DISCOVERY DESCRIPTION: 11 46 47 48 SURVEILLANCE TESTING  
FORM OF ACTIVITY RELEASED: 12 7 8 9 10 11 12 13 14 15 16 17 CONTENT OF RELEASE: 12 13 14 15 16 17 AMOUNT OF ACTIVITY: 12 13 14 15 16 17 LOCATION OF RELEASE: 12 13 14 15 16 17

## PERSONNEL EXPOSURES

13 7 8 9 10 11 12 13 14 15 16 17 NUMBER: 13 14 15 16 17 TYPE: 13 14 15 16 17 DESCRIPTION: 13 14 15 16 17

## PERSONNEL INJURIES

14 7 8 9 10 11 12 13 14 15 16 17 NUMBER: 14 15 16 17 DESCRIPTION: 14 15 16 17

## PROBABLE CONSEQUENCES

15 7 8 9 NA

## LOSS OR DAMAGE TO FACILITY

16 7 8 9 10 11 12 13 14 15 16 17 TYPE: 16 17 DESCRIPTION: 16 17

## PUBLICITY

17 7 8 9 NA

## ADDITIONAL FACTORS

18 7 8 9 SEE SUPPLEMENT

19 7 8 9

NAME: J. L. RISCHLING

PHONE: (616) 465-5901(368)

SUPPLEMENT TO REPORTABLE OCCURRENCE RO 50-315/76-30

SUPPLEMENT TO CAUSE DESCRIPTION

On the Bay 3 right door, the ice accumulation was removed and the door surface cleaned. The door seal was replaced with an improved design which in the past has proven very effective in reducing air leakage, which in turn reduces the amount of condensation and resultant ice buildup.

During an outage in April, 1976, the original door seal on the Bay 5 left door was replaced with an experimental prototype seal utilizing two sealing lips. The inspection during the July, 1976, outage indicated that the air pocket between the seal lips tends to form a nearly static air pocket which increases the ice formation from air leakage into this air pocket volume. The ice accumulation was removed from both the seal and door frame and the seal-to-door contacting surface was cleaned. To prevent this problem from reoccurring, the lower seal retainer was adjusted to permit improved seal contact in the areas of icing.

ADDITIONAL FACTORS

Technical Specification 4.6.5.3.1.b inspections for the first year of operation have been completed and the 18 month interval now applies. However, as a result of finding ice buildup on the doors, this inspection will be conducted again during or before the next refueling outage which is currently planned for late 1976.

