

50-260

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

| | | | | |
|---|--|--|------------|----------------------------------|
| TO: Mr. Norman C. Moseley | | FROM: Tennessee Valley Authority Chattanooga, Tennessee H. S. Fox | | DATE OF DOCUMENT 3/25/77 |
| <input checked="" type="checkbox"/> LETTER <input type="checkbox"/> ORIGINAL <input checked="" type="checkbox"/> COPY | | <input type="checkbox"/> NOTORIZED <input checked="" type="checkbox"/> UNCLASSIFIED | PROP | DATE RECEIVED 3/30/77 |
| | | | INPUT FORM | NUMBER OF COPIES RECEIVED 100 |

DESCRIPTION

Ltr. trans the following:

DO NOT REMOVE

PLANT NAME:

Browns Ferry Unit No. 2

(1-P)

RJL

ACKNOWLEDGED

ENCLOSURE

Licensee Event Report (RO 50-260/775) on
3/6/77 concerning drywell oxygen sensor 02M-
76-43 becoming erratic & reading erroneously
high due to grounded shields.....

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

| | |
|--------------------------|-----------|
| BRANCH CHIEF: | Schwencer |
| W/3 CYS FOR ACTION | |
| LIC. ASST.: | Sheppard |
| W/1 CYS | |
| ACRS 16 CYS HOLDING/SENT | As CAT 13 |

INTERNAL DISTRIBUTION

| | |
|--|--|
| <input checked="" type="checkbox"/> REG FILE | |
| <input type="checkbox"/> NRC PDR | |
| <input type="checkbox"/> I & E (2) | |
| <input type="checkbox"/> MIPC | |
| <input type="checkbox"/> SCHROEDER/IPPOLITO | |
| <input type="checkbox"/> HOUSTON | |
| <input type="checkbox"/> NOVAK/CHECK | |
| <input type="checkbox"/> GRIMES | |
| <input type="checkbox"/> CASE | |
| <input type="checkbox"/> BUTLER | |
| <input type="checkbox"/> HANAUER | |
| <input type="checkbox"/> TEDESCO/MACCARY | |
| <input type="checkbox"/> EISENHUT | |
| <input type="checkbox"/> BAER | |
| <input type="checkbox"/> SHAO | |
| <input type="checkbox"/> VOILLMER/BUNCH | |
| <input type="checkbox"/> KREGER/J. COLLINS | |

EXTERNAL DISTRIBUTION

| | |
|------------------|--|
| LPDR: Athens, AL | |
| TIC: | |
| NSIC: | |
| | |
| | |
| | |

CONTROL NUMBER

770900349

Handwritten mark resembling a stylized 'X' or '7' in the top right corner.

Faint, illegible text at the top of the page, possibly a header or title.

Second line of faint, illegible text.

Third line of faint, illegible text.

Fourth line of faint, illegible text.

Fifth line of faint, illegible text.

Sixth line of faint, illegible text.

Seventh line of faint, illegible text.

Eighth line of faint, illegible text.

Ninth line of faint, illegible text.


Tenth line of faint, illegible text at the bottom of the page.



TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401

REGULATORY DOCKET FILE COPY

March 25, 1977



Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., Suite 1217
Atlanta, Georgia 30303

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE
OCCURRENCE REPORT BFRO-50-260/775

The enclosed report is to provide details concerning drywell oxygen sensor 02M-76-43 which became erratic during normal operation and read erroneously high because of grounded shields. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)
CC (Enclosure):
Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



YACB

1910

1910

THE NATIONAL ARCHIVES
COLLECTIONS

THE NATIONAL ARCHIVES
COLLECTIONS

THE NATIONAL ARCHIVES
COLLECTIONS

THE NATIONAL ARCHIVES
COLLECTIONS

THE NATIONAL ARCHIVES
COLLECTIONS

THE NATIONAL ARCHIVES
COLLECTIONS

THE NATIONAL ARCHIVES
COLLECTIONS

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

| LICENSEE NAME | | | | | | LICENSE NUMBER | | | | | | | | | | LICENSE TYPE | | | | | EVENT TYPE | | | | |
|--|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|----|
| 01 | A | L | B | R | F | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 0 | 3 | |
| 8 | 9 | | | | | 14 | 15 | | | | | | | | | | | 25 | 26 | | | | 30 | 31 | 32 |

| CATEGORY | | REPORT TYPE | REPORT SOURCE | DOCKET NUMBER | | | | | | EVENT DATE | | | | | | REPORT DATE | | | | | | | | | |
|--|------|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|--|----|----|--|--|--|--|----|
| 01 | CONT | L | L | 0 | 5 | 0 | - | 0 | 2 | 6 | 0 | 0 | 3 | 0 | 6 | 7 | 7 | | | | | | | | |
| 8 | | 57 | 58 | 59 | 60 | 61 | | | | | 68 | 69 | | | | | | | 74 | 75 | | | | | 80 |

EVENT DESCRIPTION

| | | |
|--|---|----|
| 02 | During normal operation, drywell oxygen sensor O2M-76-43 became erratic and read erroneously high due to grounded shields. The redundant sensor was operable. Ground was removed and a modified sensor installed. | 80 |
| 03 | | 80 |
| 04 | | 80 |
| 05 | (BFRO-50-260/775) | 80 |
| 06 | | 80 |

| SYSTEM CODE | | CAUSE CODE | COMPONENT CODE | | | | | | PRIME COMPONENT SUPPLIER | COMPONENT MANUFACTURER | | | | VIOLATION | |
|--|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 07 | I | B | E | I | N | S | T | R | U | N | G | O | 8 | 0 | N |
| 7 | 8 | 9 | 10 | 11 | 12 | | | | 17 | 43 | | | | 47 | 48 |

CAUSE DESCRIPTION

| | | |
|--|---|----|
| 08 | The GE oxygen sensor signal was erratic due to shorted shield to ground causing ground loop which affected sensor output. Modified sensor installed and checked out satisfactorily. | 80 |
| 09 | | 80 |
| 10 | | 80 |

| FACILITY STATUS | | % POWER | | OTHER STATUS | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | |
|--|---|---|---|---|--|---|----|--|----|
| 11 | E | 0 | 9 | 9 | NA | A | | NA | |
| 7 | 8 | 9 | 10 | 12 | 13 | 44 | 45 | 46 | 80 |

| FORM OF ACTIVITY RELEASED | | CONTENT OF RELEASE | | AMOUNT OF ACTIVITY | | LOCATION OF RELEASE | |
|--|---|---|----|--|----|--|----|
| 12 | Z | Z | | NA | | NA | |
| 7 | 8 | 9 | 10 | 11 | 44 | 45 | 80 |

PERSONNEL EXPOSURES

| NUMBER | | TYPE | DESCRIPTION |
|--|---|---|--|
| 13 | 0 | Z | NA |
| 7 | 8 | 9 | 11 |

PERSONNEL INJURIES

| NUMBER | | DESCRIPTION |
|--|---|--|
| 14 | 0 | NA |
| 7 | 8 | 11 |

OFFSITE CONSEQUENCES

| | | |
|--|--|----|
| 15 | NA | 80 |
|--|--|----|

LOSS OR DAMAGE TO FACILITY

| TYPE | DESCRIPTION |
|--|--|
| 16 | NA |
| 7 | 10 |

PUBLICITY

| | | |
|--|--|----|
| 17 | NA | 80 |
|--|--|----|

ADDITIONAL FACTORS

| | | |
|--|--|----|
| 18 | NA | 80 |
|--|--|----|

| | | |
|--|--|----|
| 19 | | 80 |
|--|--|----|

NAME

PHONE

1977 MAR 31 AM 9 36

RECEIVED DOCUMENT
PROCESSING UNIT

25 MAR 77