

50-260

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr Moseley

FROM: Tennessee Valley Authority
Chattanooga, Tn
H S FoxDATE OF DOCUMENT
8-13-76DATE RECEIVED
8-17-76☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

464/ 1cc

DESCRIPTION

- Ltr trans the following:

ENCLOSURE

Licensee Event Report (RO#BFRO-50-260/769)
on 7-21-76 concerning alarm which was re-
ceived from a smoke detector in the control
room.....

PLANT NAME: Browns Ferry #2

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

8-18-76

ehf

BRANCH CHIEF:

Schwencer

W/3 CYS FOR ACTION

LIC. ASST.:

Sheppard

W/1 CYS

ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

REG FILE

NRC-PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

CASE

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: Athens, Ala

TIC:

NSIC:

CONTROL NUMBER

8344

Mr. Mosley

Tennessee Valley Authority
Chattanooga, TN
H. S. Fox

8-13-76

8-17-76

Wdy \ Jcc

Licensee Event Report (RO BR90-20-260\769)
on 7-21-76 concerning alarm which was re-
ceived from a smoke detector in the control
room.....

Let arms the following:

Browns Ferry 42

8-17-76 whf



TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

August 13, 1976

Regulatory Division



Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303

Dear Mr. Moseley:


TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DFR-52 - REPORTABLE
OCCURRENCE REPORT BFR0-50-260/769

The enclosed report is to provide details concerning an alarm which was received from a smoke detector in the control room due to increased sensitivity. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry Nuclear Plant unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production



Enclosure (3)
CC (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8344

LICONSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME

LICENSE NUMBER

LICENSE TYPE

EVENT TYPE

01 A L B R F 2 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 0 3

CATEGORY

REPORT TYPE

REPORT SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

01 CONT L L 0 5 0 - 0 2 6 0 0 7 2 1 7 6 7 5 8 0

EVENT DESCRIPTION

02 An alarm was received from a smoke detector in the control room due to increased
03 sensitivity. The detector was cleaned and returned to normal. BFRO-50-260/769
04
05
06

SYSTEM CODE

CAUSE CODE

COMPONENT CODE

PRIME COMPONENT SUPPLIER

COMPONENT MANUFACTURER

VIOLATION

07 A B E I N S T R U L K 1 2 0 N

CAUSE DESCRIPTION

08 Kidde smoke detector needed cleaning.
09
10

FACILITY STATUS

% POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

11 H 0 0 0 NA A NA

FORM OF ACTIVITY RELEASED

CONTENT OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

12 Z Z NA NA

PERSONNEL EXPOSURES

NUMBER

TYPE

DESCRIPTION

13 0 0 0 Z NA

PERSONNEL INJURIES

NUMBER

DESCRIPTION

14 0 0 0 NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE DESCRIPTION

16 Z NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 Gradual accumulation of dust causes increased smoke detector sensitivity.

19

PHONE:

