

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 757

FILE: INCIDENT REPORT

FROM: Tennessee Valley Auth. Chattanooga, Tenn. 37401 J.E. Gilleland			DATE OF DOC 1-20-75	DATE REC'D 1-23-75	LTR XXX	TWX	RPT	OTHER
TO: Mr. E. CASE			ORIG 1 signed	CC OTHER	SENT AEC PDR SENT LOCAL PDR		XX XX	
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-259/260			

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Browns Ferry Plant Units 1 & 2
NonRoutine 30-Day Report re failure in the
piping system....

ACKNOWLEDGED

(1 cy encl rec'd)

Do Not Remove

PLANT NAME: Browns Ferry 1 & 2

FOR ACTION/INFORMATION

DHL 1-24-75

BUTLER (S) W/ Copies	SCHWENCER (S) W/ Copies	ZIEMANN (S) W/ Copies	REGAN (E) W/ Copies
CLARK (S) W/ Copies	STOLZ (S) W/ Copies	DICKER (E) W/ Copies	LEAR (S) W/ Copies
PARR (S) W/ Copies	VASSALLO (S) W/ Copies	KNIGHTON (E) W/ Copies	SPEIS (S) W/ Copies
KNIEL (S) W/ Copies	PURPLE (S) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

<u>REG FILE (2)</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC. ASST.</u>	<u>A/T IND</u>
✓ AEC PDR (2)	✓ SCHROEDER	GRIMES	DIGGS (S)	BRAITMAN
✓ CGC, ROOM P-506-A	✓ MACCARRY	GAMMILL	GEARIN (S)	SALTZMAN
✓ UNIZING/STAFF	✓ KNIGHT	✓ KASTNER	✓ GOULBOURNE (S)	B. HURT
✓ CASE	✓ PAWLICKI	BALLARD	KREUTZER (E)	
GIAMBUSSO	✓ SHAO	SPANGLER	LEE (S)	<u>PLANS</u>
BOYD	✓ STELLO		MAIGRET (S)	MCDONALD
MOORE (S) (BWR)	✓ HOUSTON	<u>ENVIRO</u>	REED (E)	CHAPMAN
DEYOUNG (S) (PWR)	✓ NOVAK	MULLER	SERVICE (S)	DUBE w/input
SKOVHOLT (S)	✓ CROSS	DICKER	SHEPPARD (S)	E. COUPE
GOLLER (S)	✓ IPPOLITO	KNIGHTON	SLATER (E)	✓ R. Hartfield (2)
P. COLLINS	✓ TEDESCO	YOUNGBLOOD	✓ SMITH (S)	✓ KLECKER
DENISE	✓ LONG	REGAN	TEETS (S)	✓ F. WILLIAMS
REG. OPR	✓ LAINAS	PROJECT LDR	WILLIAMS (E)	
✓ FILE & REGION (2)	✓ BENAROYA		WILSON (S)	
✓ T.R. WILSON	✓ STEELE	✓ VOLIMER	INGRAM (S)	
		HARLESS		

EXTERNAL DISTRIBUTION

✓ 1-LOCAL PDR Athens, Ala.	(1) (2) (10) - NATIONAL LABS	1-PDR SAN/LA/NY
✓ 1-TIC (ABERNATHY)	1-M. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
✓ 1-NSIC (BUCHANAN)	1-CONSULTANTS	1-G. ULRIKSON, ORNL
1-ASLB	NEWMARK/BLUME/ACBABIAN	1-AGMED (RUTH GUSSMAN)
1-NEWTON ANDERSON		RM B-127 G.T.
✓ 5-ACRS SENT TO LIC. ASST.		1-J. RUNKLES, RM E-201
✓ H. Smith 1-24-75		G.T.


BN

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

Regulatory Docket File

January 20, 1975



Mr. Edson G. Case
Acting Director of Licensing
Office of Regulation
U.S. Atomic Energy Commission
Washington, DC 20545

Dear Mr. Case:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT
UNITS 1 AND 2 - DOCKET NOS. 50-259, 50-260 - FACILITY
OPERATING LICENSE DPR-33, DPR-52

The enclosed report, submitted as required by Browns Ferry Nuclear Plant Technical Specification 6.7.2.B(3), is to provide details concerning Browns Ferry's units 1 and 2 control bay air conditioning equipment. It was discovered on December 19, 1974, that the control bay air conditioning equipment could be disabled by a single failure.

Very truly yours,


J. E. Gilleland

Assistant to the Manager of Power

Enclosure

CC (Enclosure):

Mr. Norman C. Moseley, Director
Directorate of Regulatory Operations
U.S. Atomic Energy Commission
Region II - Suite 818
230 Peachtree Street, NW.
Atlanta, Georgia 30303



ENCLOSURE

Regulatory Docket File

BROWNS FERRY NUCLEAR PLANT UNITS 1 AND 2

NONROUTINE 30-DAY REPORT

Revised 10/1/75 1-26-75

Description of Occurrence

Certain single failures in the piping system of the control bay air conditioning equipment (CBACE) could result in the loss of cooling water to all control bay cooling equipment.

Causes of Deficiency

The deficiency arises due to the fact that the normal and emergency water supplies to the control bay chillers share a common distribution header. The discharge lines have a similar situation.

Safety Implications

Since the operability of the control bay air conditioning equipment must be assured, system separation will be desirable to increase reliability. This will require a provision for separate operation of the emergency cooling equipment from the normal control bay air conditioning system.

Corrective Measures

Seismically qualified piping and valves will be added to the existing system to obtain the desired separation. This involves connecting the EECW water supply directly to the emergency chiller and providing separate discharge piping from this chiller into the EECW discharge conduit. ECN-L1321 was issued to make these design changes. Corrective measures will be implemented by March 15, 1975.