

DSB



**Consumers
Power
Company**

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

June 19, 1980

Mr James G Keppler
Office of Inspection and Enforcement
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

DOCKET 50-255 - LICENSE DPR-20 -
PALISADES PLANT - LICENSEEE EVENT
REPORT 80-018 - SNUBBER FAILURE

On the reverse side is Licensee Event Report 80-018 which is reportable under
Technical Specification 6.9.2.B.2.

Roger W Huston
Senior Licensing Engineer

CC Director, Office of Nuclear Reactor Regulation
Director, Office of Inspection and Enforcement
NRC Resident Inspector - Palisades

1002
3.11

JUN 23 1980

LICENSEE EVENT REPORT

CONTROL BLOCK: 1										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
M I P A L 1										2 0 0 - p 0 0 0 0 - 0 0 3 4 1 1 1 1 4									
LICENSEE CODE										LICENSE NUMBER									
CON'T										REPORT SOURCE									
L 0 5 0 0 0 2 5 5 7 0 5 2 2 8 0 8 0 6 1 9 8 0 9										DOCKET NUMBER									
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10										EVENT DATE									
0 2 During routine testing of hydraulic snubbers, the oil level in snubber										REPORT DATE									
0 3 No. 2 was found to be less than zero, and the snubber was declared										80									
0 4 inoperable. Event reportable per T.S. 6.9.2.B.2 and 3.20. See LER																			
0 5 80-14 thru 80-16 for similar occurrences.																			
0 6																			
0 7																			
0 8																			
SYSTEM CODE										CAUSE CODE									
H B 11										E 12									
COMPONENT CODE										COMP. SUBCODE									
S U P O R T 14										D 15									
VALVE SUBCODE										Z 16									
LER/RO REPORT NUMBER										EVENT YEAR									
8 0										1 8									
ACTION TAKEN										FUTURE ACTION									
C 18										Z 19									
EFFECT ON PLANT										SHUTDOWN METHOD									
Z 20										Z 21									
HOURS										ATTACHMENT SUBMITTED									
0 0 0 0										N 23									
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27										NPRD-4 FORM SUB.									
The cause of fluid leakage is apparent seal degradation. The snubber										PRIME COMP. SUPPLIER									
will be disassembled to confirm the cause.										A 25									
1 2										B 2 1 0 26									
1 3																			
1 4																			
FACILITY STATUS										METHOD OF DISCOVERY									
G 28										B 31									
% POWER										DISCOVERY DESCRIPTION 32									
0 0 0 0 29 NA										Surveillance Test									
ACTIVITY CONTENT										AMOUNT OF ACTIVITY 35									
RELEASED OF RELEASE										LOCATION OF RELEASE 36									
Z 33										NA									
PERSONNEL EXPOSURES										PERSONNEL INJURIES									
NUMBER										DESCRIPTION 39									
0 0 0 37										Z 38 NA									
PERSONNEL INJURIES										LOSS OF OR DAMAGE TO FACILITY									
NUMBER										TYPE									
0 0 0 40										Z 42									
PUBLICITY										ISSUED DESCRIPTION 45									
N 44										NA									
2 0										NRC USE ONLY									