




**Consumers
Power
Company**

P. L. Leland
REGULATORY DOCKET FILE COPY

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

October 10, 1977

Mr James G Keppler
Office of Inspection and Enforcement
Region III
US Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



DOCKET 50-255 - LICENSE DPR-20 -
PALISADES PLANT - CORRECTED
ER-77-029 AND ER-77-038

Attached are two corrected Event Reports 77-029 and 77-038 for the Palisades Plant.

ER-77-029 was erroneously classified as a 30-day report when it should have been classified as a prompt report.

ER-77-038 has been changed to reflect a violation of Technical Specifications as a result of IE Inspection Report 77-11.

David P. Hoffman

David P Hoffman
Assistant Nuclear Licensing Administrator

CC: ASchwencer, USNRC

OCT 12 1977

CORRECTED

LICENSEE EVENT REPORT

Palisades

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 M I P A L 1
LICENSE NUMBER: 00-000000-00
LICENSE TYPE: 41111
EVENT TYPE: 01
REPORT TYPE: 01 CONT * *
REPORT SOURCE: T L
DOCKET NUMBER: 050-0255
EVENT DATE: 060877
REPORT DATE: 070877

EVENT DESCRIPTION

02 Routine once-per-shift checks identified a high level condition for safety injection
03 tank, T82C, which exceeded Technical Specification 3.3.1.b requirements by 1.6 percent.
04 The other three tanks were within specifications. The level was adjusted to bring
05 T82C within specifications.
06 (ER-77-029)

SYSTEM CODE: S F
CAUSE CODE: E
COMPONENT CODE: I N S T R U
PRIME COMPONENT SUPPLIER: A
COMPONENT MANUFACTURER: F 1 8 0
VIOLATION: Y

CAUSE DESCRIPTION

08 On 6/8/77 a Deviation Report was initiated for the "as found" indication for C safety
09 injection bottle level transmitter/indicator. It was found that instrument drift
10 (specifically zero drift) had produced a 3-4 percent error in level indication. The
(Contd on Attached Sheet)

FACILITY STATUS: E
% POWER: 100
OTHER STATUS: NA
METHOD OF DISCOVERY: b
DISCOVERY DESCRIPTION: Normal once-a-shift log sheet readings.

FORM OF ACTIVITY RELEASED: Z
CONTENT OF RELEASE: Z
AMOUNT OF ACTIVITY: NA
LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

13 NUMBER: 000
TYPE: Z
DESCRIPTION: NA

PERSONNEL INJURIES

14 NUMBER: 000
DESCRIPTION: NA

PROBABLE CONSEQUENCES

15 See the attached sheet.

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z
DESCRIPTION: NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19

Cause Description Continued From Line 10

instrument was recalibrated and an evaluation was performed of the consequences of this error assuming that it had existed over the previous five months. While this evaluation was in progress, the C SI bottle level was found to be 60% (1.6 percent above the Technical Specifications limit) at 0015 on 6/8/77. The level was returned to within specifications by 0100 the same morning. Meanwhile, the concurrent investigation revealed that numerous violations from 1 to 2 percent below the Technical Specifications limit had occurred for C bottle under the above assumption. The discrepancy developed due to conflicts between the bottle level indicators and high-low level switch alarms.

Probable Consequences From Line 15

Since the violations described above are of such similar nature, they are being treated in a single event report. It should be noted that since the violations occurred for only one of the four SI bottles and that the other three had normal levels, the total volume available in each instance for a safety injection was certainly within acceptable limits.

CORRECTED
LICENSEE EVENT REPORT

Palisades

[PLEASE PRINT ALL REQUIRED INFORMATION]

CONTROL BLOCK:

--	--	--	--	--	--

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE				EVENT TYPE					
01	M	I	P	A	L	1	0	0	-	0	0	0	0	0	4	1	1	1	1	0	1
7	8	9				14	15							25	26				30	31	32

REPORT TYPE		REPORT SOURCE		DOCKET NUMBER				EVENT DATE				REPORT DATE													
01	CONT	*	*	T	L	0	5	0	-	0	2	5	5	0	8	1	4	7	7	0	8	2	6	7	7
7	8			57	58	59	60	61					68	69					74	75					80

EVENT DESCRIPTION

02	During the quarterly testing of the containment penetration No 4, purge air exhaust,																						
03	the penetration did not hold the minimum required pressure per Tech Spec 4.5.2. The																						
04	plant was shut down within the required 48 hours and repairs initiated to repair																						
05	Fisher Continental butterfly valve (CV-1805). (ER-77-038)																						
06																							

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	S	D	E	V	A	L	V	E	X	A	F	1	2	5	Y
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	The valve is a 48" butterfly valve with pressurized rubber seats. Inspection of the																						
09	seat showed that it was badly worn from interaction with the valve disc. Normal wear																						
10	may have been compounded by improper timing of the valve seat pressurization with																						

(contd on Line 18)

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
11	E	1	0	0	commenced shutdown				b	NA				
7	8	9	10	11	12	13		44	45	46				80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE					
12	Z	Z	NA				NA						
7	8	9	10	11				44	45				80

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION	
13	0	0	0	Z	NA	
7	8	9	11	12	13	

PERSONNEL INJURIES

NUMBER			DESCRIPTION	
14	0	0	0	NA
7	8	9	11	12

PROBABLE CONSEQUENCES

15	NA																						
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	NA	
7	8	9	10

PUBLICITY

17	NA																						
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS Continued from "Cause Description"

18	valve closure. The valve is designed so that after the valve is fully closed, the rubber seat is pressurized to force the seat against the valve disc. Inspection procedures have been modified to emphasize proper timing of seat pressurization.																						
19																							