




*D. Latham*

**Consumers  
Power  
Company**

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

May 20, 1976



Mr James G. Keppler  
Office of Inspection Enforcement  
Region III  
US Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137


DOCKET 50-255, LICENSE DPR-20 -  
PALISADES PLANT - ER-76-10 -  
CHARGING PUMP P55-A

Attached is a reportable occurrence which relates to the Palisades Plant.  
This occurrence has been classified as a thirty-day reportable event.

*David A. Bixel*

David A. Bixel  
Assistant Nuclear Licensing Administrator

Regulatory Docket File




5498

MAY 24 1976

**LICENSEE EVENT REPORT**

Palisades

CONTROL BLOCK: 

**[PLEASE PRINT ALL REQUIRED INFORMATION]**

LICENSEE NAME						LICENSE NUMBER							LICENSE TYPE					EVENT TYPE						
01	M	I	P	A	L	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9			14	15										25	26				30	31	32	

REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE						REPORT DATE								
01	CONT			L	0	5	0	-	0	2	5	5	0	4	2	1	7	6	0	5	2	0	7	6
7	8	57	58	59	60	61						88	69				74	75					80	

### EVENT DESCRIPTION

02	During testing (RO-8, Loss of Off-Site Power/SIS Test) the charging pump (P55-A)	80
03	failed to perform properly. Analysis of the test results disclosed that the pump	80
04	started and ran for 10 seconds before shutting down. The standby pump (P55-B)	80
05	started following trip of P55-A and provided the necessary capacity.	80
06	(ER-76-10)	80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE						COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
0	7	R	B	A	F	I	L	T	E	R	N	M	0	7	5	Y
7	8	9	10	11	12					17	43	44			47	48

**CAUSE DESCRIPTION**

08	The pump trip resulted from a plugged oil filter. This filter has been changed	80
7 8 9		
09	and the pump operates satisfactorily. This filter change requirement is on our	80
7 8 9		
10	preventative maintenance schedule. However, this maintenance was delayed for	80
7 8 9		

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	G	0	0	0	NA		b	NA		
7	9	10	11	12	13	14	15	16	17	18

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	2	Z		NA		NA	
7	8	9	10	11	44	45	80

## PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	Z NA

## PERSONNEL INJURIES

NUMBER			DESCRIPTION
1	4	000	NA

### PROBABLE CONSEQUENCES

15 None - Redundant equipment available.

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	NA

## PUBLICITY

17	NA	80
----	----	----

## ADDITIONAL FACTORS

18 | about four months due to the refueling outage. The necessity of adhering to PM

19 | work will be reviewed with the maintenance supervisors. | 80