

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 V A N A S I ② 0 0 - 0 0 0 0 0 0 - 0 0 ③ 4 1 1 1 1 1 ④ ⑤
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L ⑥ 0 5 0 0 0 3 3 8 ⑦ 0 1 7 1 2 1 6 7 9 ⑧ 0 1 8 1 1 7 7 9 ⑨
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 During mode 1 operations, fire door S54-11, between Unit 2 emergency switchgear room
0 3 and the turbine building, was found to be non-functional. This resulted in degradat-
0 4 ion of the control room fire boundary. This event did not jeopardize the health and
0 5 safety of the general public. Reportable pursuant to T.S. 6.9.1.9.b.
0 6
0 7
0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
7 8 9 10 11 12 13 18 19 20
S G ⑪ A ⑫ B ⑬ Z Z Z Z Z Z ⑭ Z ⑮ Z ⑯
17 LER/RO REPORT NUMBER ⑰ EVENT YEAR 21 22 23 SEQUENTIAL REPORT NO. 24 26 27 OCCURRENCE CODE 28 29 REPORT TYPE 30 31 REVISION NO. 32
7 8 9 10 11 12 13 18 19 20
7 9 ⑰ ① 0 9 1 3 ⑱ 0 3 ⑲ L ⑳ 0 ㉑
18 ACTION 33 19 FUTURE ACTION 34 20 EFFECT ON PLANT 35 21 SHUTDOWN METHOD 36 22 HOURS 37 23 ATTACHMENT SUBMITTED 40 41 24 NPRD-4 FORM 108 42 25 PRIME COMP. SUPPLIER 43 26 COMPONENT MANUFACTURER 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

1 0 Temporary hoses supplying cooling water to a battery load tester were running through
1 1 the fire door preventing full closure. A fire watch was posted and the hoses were
1 2 disconnected and removed. Applicable area logs will be revised to check fire doors
1 3 closed every 4 hrs.
1 4

1 5 FACILITY STATUS ⑳ 28 1 0 0 0 ⑲ 29 NA ③① Operator Observation ③②
7 8 9 10 11 12 13 44 45 46
1 6 ACTIVITY CONTENT ③③ ③④ NA ③⑤ AMOUNT OF ACTIVITY ③⑥ LOCATION OF RELEASE ③⑦
7 8 9 10 11 12 13 44 45 46
1 7 PERSONNEL EXPOSURES ③⑧ ③⑨ NA ③⑩
7 8 9 10 11 12 13 44 45 46
1 8 PERSONNEL INJURIES ③⑪ ③⑫ NA ③⑬
7 8 9 10 11 12 13 44 45 46
1 9 LOSS OF OR DAMAGE TO FACILITY ③⑭ ③⑮ NA ③⑯
7 8 9 10 11 12 13 44 45 46
2 0 PUBLICITY ③⑰ ③⑱ NA ③⑲
7 8 9 10 11 12 13 44 45 46

NRC USE ONLY

NAME OF PREPARER W. R. Cartwright

7908240493

PHONE: 703-894-5151

Description of Event

On July 26, 1979, during mode 1 operations, fire door S54-11 was discovered not functional in accordance with Technical Specification 3.7.15. This door is in the Unit 2 Emergency Switchgear and Relay Room. It shares, however, a common habitability with the Unit 1 Switchgear and Relay Room.

Probable Consequences of Occurrence

The penetration fire barriers required by T.S. 3.7.15 are provided to assure continuous occupancy of the area during and after normal phenomena, fire and missiles as well as for all postulated accidents which may or may not release radioactivity to the environs. In this case, door S54-11 is used both as a pressure envelope boundary and a penetration fire barrier. The health and safety of operating personnel and the general public were not affected by this event.

Cause

Temporary hoses supplying cooling water to a battery load tester were running through the fire door preventing the door from fully closing.

Immediate Corrective Action

A fire watch was stationed to insure complete closure in order to maintain administrative control of the pressure boundaries and the hoses were disconnected and removed from between the door.

Scheduled Corrective Actions

Applicable area logs will be revised to check fire doors closed every 4 hours. Also signs will be placed on all fire doors instructing personnel to keep doors closed at all times to maintain the required control room fire boundary.

Actions Taken to Prevent Recurrence

The scheduled corrective actions will prevent recurrence of the problem.