

LICENSEE EVENT REPORT

CONTROL BLOCK:

							①
--	--	--	--	--	--	--	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	37	CA	58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 8 0 3 7 9 8 0 8 3 0 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a normal reactor startup, "full out" indication was not received when rod 42-23

03 was pulled to position 48. All individual indications indicated that the rod was at

0	4
---	---

 notch 48, or "full out".

0	5	Technical Specifications 3.1.3.7, 6.9.1.9b
---	---	--

17	REPORT NUMBER	7	9	—	0	6	7	—	0	3	L	—	0
		21	22	23	24	25	26	27	28	29	30	31	32

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 An investigation revealed that the problem is in the PIP probe located in the drywell.

11 The problem will be corrected during the next outage of sufficient length.

1	2	
---	---	--

1	3	
---	---	--

1	4	
---	---	--

1	5	C	(28)	0	1	0	(29)	NA	A	(31)	Operator Surveillance
---	---	---	------	---	---	---	------	----	---	------	-----------------------

1	6	Z	(33)	Z	(34)	NA	NA
---	---	---	------	---	------	----	----

NUMBER			TYPE		DESCRIPTION
1	7	0 0 0	37	Z	(23) NA

[illegible]

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE	DESCRIPTION

916123

1	9	Z	(47)	NA
---	---	---	------	----

8 9 10 PUBLICITY

***** 131

NDC USE ONLY

ISSUED		DESCRIPTION (4b)	7909060136		NRC USE ONLY	
1	2	3	4	5	6	7
1	2	3	4	5	6	7

[illegible]