

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK

PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION

0 1 A R A N O 2 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 56

CON'T

0 1 REPORT SOURCE L 0 5 0 0 0 3 6 8 7 0 8 1 2 7 8 0 9 0 5 7 9 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 During Mode 2 operation, Emergency Feedwater flow control valve, 2CV-1025,

0 3 1, from the electric driven EFW pump, 2P7B, to the "A" steam generator,

0 4 failed to fully close from a Control Room demand signal. The redundant

0 5 EFW valves were successfully stroked from the Control Room. This occur-

0 6 rence is similar to LER 50-368/79-051, 79-043, 79-035, and 78-28.

0 7 Reportable per T.S.6.9.1.9b.

0 8

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

W B 11 E 12 B 13 V A L V 14 P 15 A 16 Z 16

LER NO. REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION

7 9 1 0 6 8 3 L 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC/IA FORM 501 PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

F 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 W 1 2 7 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 Investigation revealed that the limit stop switch was out of alignment.

1 1 Realignment was made and the valve was successfully stroke tested. The

1 2 valve was declared operable within 7 hours, meeting the requirement of

1 3 Action Statement T.S. 3.7.1.2.

1 4

FACILITY STATUS POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

B 28 P 29 NA A 31 NA

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

Z 33 Z 34 NA NA

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

0 37 Z 38 NA

PERSONNEL INJURIES NUMBER DESCRIPTION

0 40 NA

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

Z 42 NA

PUBLICITY ISSUED DESCRIPTION

N 44 NA

NRC USE ONLY

NAME OF PREPARER Chris N. Shively

501/968-2519

943 136

7909120 566