

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1			D	C	C	N		(2)	0	0	-	0	0	0	0	0	-	0	0	(3)	4	1	1	1	1	(4)			(5)		
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	31	CAT		38

CON'T

0 1
7 8

REPORT SOURCE L 6 0 5 0 0 0 3 1 7 7 0 8 1 1 7 9 8 0 9 1 0 7 9 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 0130 the Control Room Operator noticed that the containment air particulate

[03] | monitor had failed. The monitor was declared inoperable per T.S. 3.4.6.1. The

04 | containment particulate monitor was returned to service at 1345. The containment

05 | gaseous monitor and containment sump level alarm remained operable during the

06 | event. LER 78-28 (U-2) describes a similar event.

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
----------------	---------------	------------------	----------------	------------------	------------------

0 9 8 9 10 11 12 13 14 15 16

LER NO	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION
17101	1961	10101	1000	TYPE	1.0

REPORT NUMBER

7	9
---	---

—

0	3	5
---	---	---

/

0	3
---	---

L

—

5

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		APRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of the low indication was due to the detector tube giving low response

11 (Westinghouse P/N 2372A80-H01). Tube failure was probably caused by dirt on its

1 2 socket assembly, which was cleaned. The detector was replaced. No preventive

1 2 | action is necessary. (See attached for further details)

14

FACILITY

(30) METHOD OF

STATUS		POWER		OTHER STATUS		DISCOVERY		DISCOVERY DESCRIPTION				
1	5	E	18	0	9	5	29	NA	A	31	Operator Observation	32

[illegible]

1 6 2 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL EXPOSURES			29
NUMBER	TYPE	DESCRIPTION	
1	1	1	
2	2	2	
3	3	3	
4	4	4	
5	5	5	
6	6	6	
7	7	7	
8	8	8	
9	9	9	
10	10	10	
11	11	11	
12	12	12	
13	13	13	
14	14	14	
15	15	15	
16	16	16	
17	17	17	
18	18	18	
19	19	19	
20	20	20	
21	21	21	
22	22	22	
23	23	23	
24	24	24	
25	25	25	
26	26	26	
27	27	27	
28	28	28	
29	29	29	
30	30	30	
31	31	31	
32	32	32	
33	33	33	
34	34	34	
35	35	35	
36	36	36	
37	37	37	
38	38	38	
39	39	39	
40	40	40	
41	41	41	
42	42	42	
43	43	43	
44	44	44	
45	45	45	
46	46	46	
47	47	47	
48	48	48	
49	49	49	
50	50	50	

7 8 9 10 11 12 13 NA 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

DATE	DESCRIPTION	AMOUNT	INITIALS
10/1/54	100.00	100.00	
10/2/54	100.00	100.00	
10/3/54	100.00	100.00	
10/4/54	100.00	100.00	
10/5/54	100.00	100.00	
10/6/54	100.00	100.00	
10/7/54	100.00	100.00	
10/8/54	100.00	100.00	
10/9/54	100.00	100.00	
10/10/54	100.00	100.00	
10/11/54	100.00	100.00	
10/12/54	100.00	100.00	
10/13/54	100.00	100.00	
10/14/54	100.00	100.00	
10/15/54	100.00	100.00	
10/16/54	100.00	100.00	
10/17/54	100.00	100.00	
10/18/54	100.00	100.00	
10/19/54	100.00	100.00	
10/20/54	100.00	100.00	
10/21/54	100.00	100.00	
10/22/54	100.00	100.00	
10/23/54	100.00	100.00	
10/24/54	100.00	100.00	
10/25/54	100.00	100.00	
10/26/54	100.00	100.00	
10/27/54	100.00	100.00	
10/28/54	100.00	100.00	
10/29/54	100.00	100.00	
10/30/54	100.00	100.00	
10/31/54	100.00	100.00	
TOTAL	3000.00	3000.00	

7 8 9 11 12 ORIGINAL 334 30

100-443887-1000
 7909130-7
 ORIGINAL

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

SECRET NA 340268

S. M. Davis/P. G. Rizzo (301) 234-7342/46

NAME OF PATENT: _____

S. M. Davis/P. G. Rizzo

2-543

(GOI) 234-7342/46

NAC USE ONLY

LER NO. 79-35/3L
EVENT DATE 08-11-79
REPORT DATE 09-10-79
DOCKET NO. 50-317
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

An unusual amount of heavy work in the Containment building during the recent refueling outage caused the sampler to draw in much dust and dirt. A routine surveillance test would have included disassembly of the detector assembly during the outage. However, the surveillance test was performed early in 1979 during an unplanned outage. Due to the lengthy outages and the type of work performed in the containment building, more dust and dirt was drawn through the sampler lines than is expected normally.

POOR
ORIGINAL

945168