

CONTROL BLOCK: | | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 7920 Technical Specification Involved 3.7.A.5.a/3.7.A.6
Reported Under Technical Specification 6.7.2.b.2
Date of Occurrence 8/31/79 Time of Occurrence 1237 Unit 1

Identification and Description of Occurrence:

In preparation for a planned reactor shutdown for maintenance, containment oxygen concentration exceeded 4% and drywell-suppression chamber differential pressure decreased below 1.0 psid.

Conditions Prior to Occurrence:

Unit one - operating at 95% power.

POOR
ORIGINAL

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Establish cold shutdown condition within 24 hours if containment inertion and differential pressure requirements cannot be met.

Apparent Cause of Occurrence:

Deferment of planned unit one shutdown due to unplanned shutdown of unit two.

Analysis of Occurrence:

There was no hazard to the public health or safety.


Corrective Action:

Reinerted containment and reestablished drywell-suppression chamber differential pressure.

Failure Data:

None previous.

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

1083 118