

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M D C C N 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 57 CAT 58

CON'T
01 REPORT SOURCE L 6 0 5 0 0 0 3 1 7 7 0 8 2 9 7 9 8 0 9 2 8 7 9 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing a routine surveillance test, it was discovered that the 115
03 volt power supply to hydrogen analyzer O-AE-6527 was inoperative (T.S.3.6.5.1).
04 Hydrogen analyzer O-AE-6527 was repaired and returned to service on 8/31/79. The
05 redundant hydrogen analyzer remained in operation throughout this event. This
06 has not been a repetitive event.

07

08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
S E 11 E 12 A 13 I N S T R U 14 P 15 Z 16

17 LER/RO REPORT NUMBER 7 9 21 22
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 N 24 A 25 0 0 9 6 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Troubleshooting disclosed the Delphi Model B1B power transformer T-1 had a
11 shorted secondary winding. There was no other failed component which may have
12 been a primary cause for transformer failure. The occurrence is considered to
13 be an end-of-life failure; no preventive action is necessary.

14

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 28 0 9 9 29 NA B 31 Surveillance Test

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 NA

18 PERSONNEL INJURIES NUMBER TYPE DESCRIPTION
0 0 0 40 NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 NA

20 PUBLICITY ISSUED DESCRIPTION
Z 44 NA

NAME OF PREPARER R. P. Heibel/P. G. Rizzo

PHONE (301) 234-7943/7986

1033 343
7910030494

NRC USE ONLY