

CONTROL BLOCK: 1 2 3 4 5 6 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y J A F I (2) 0 0 - 0 0 0 0 - 0 0 0 (3) 4 1 1 1 1 (4) (5)

7 8 9 14 15 25 26 30 5/ CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

|   |   |
|---|---|
| 0 | 1 |
| 7 | 8 |

REPORT SOURCE

|               |    |   |   |   |   |   |   |   |    |            |   |   |   |   |    |             |   |   |   |   |   |   |    |
|---------------|----|---|---|---|---|---|---|---|----|------------|---|---|---|---|----|-------------|---|---|---|---|---|---|----|
| L             | 6  | 0 | 5 | 0 | 0 | 3 | 3 | 3 | 7  | 0          | 9 | 0 | 5 | 1 | 9  | 8           | 1 | 0 | 0 | 3 | 7 | 9 | 9  |
| 60            | 61 |   |   |   |   |   |   |   | 68 | 69         |   |   |   |   | 74 | 75          |   |   |   |   |   |   | 80 |
| DOCKET NUMBER |    |   |   |   |   |   |   |   |    | EVENT DATE |   |   |   |   |    | REPORT DATE |   |   |   |   |   |   |    |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

|   |   |                       |
|---|---|-----------------------|
| 0 | 2 | Please See Attachment |
| 0 | 3 |                       |
| 0 | 4 |                       |
| 0 | 5 |                       |
| 0 | 6 |                       |
| 0 | 7 |                       |
| 0 | 8 |                       |

|                      |   |             |    |                     |    |                 |            |             |    |          |                |              |    |               |    |                 |    |                 |    |       |    |                      |    |                  |    |                      |    |                        |    |    |    |    |    |    |    |    |    |    |    |    |
|----------------------|---|-------------|----|---------------------|----|-----------------|------------|-------------|----|----------|----------------|--------------|----|---------------|----|-----------------|----|-----------------|----|-------|----|----------------------|----|------------------|----|----------------------|----|------------------------|----|----|----|----|----|----|----|----|----|----|----|----|
| 0                    | 9 | SYSTEM CODE |    | S                   | F  | 11              | CAUSE CODE |             | D  | 12       | COMPONENT CODE |              |    |               |    |                 | I  | N               | S  | T     | R  | U                    | 14 | COMP. SUBCODE    |    | S                    | 15 | VALVE SUBCODE          |    | Z  | 16 |    |    |    |    |    |    |    |    |    |
| 7                    | 8 | 9           | 10 | 11                  | 12 | 13              | 14         | 15          | 16 | 17       | 18             | 19           | 20 | 21            | 22 | 23              | 24 | 25              | 26 | 27    | 28 | 29                   | 30 | 31               | 32 | 33                   | 34 | 35                     | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 |
| LER RO REPORT NUMBER |   | EVENT YEAR  |    | SEQUENCE REPORT NO. |    | OCCURRENCE CODE |            | REPORT TYPE |    | REVISION |                | ACTION TAKEN |    | FUTURE ACTION |    | EFFECT ON PLANT |    | SHUTDOWN METHOD |    | HOURS |    | ATTACHMENT SUBMITTED |    | NPRD-4 FORM SUB. |    | PRIME COMP. SUPPLIER |    | COMPONENT MANUFACTURER |    |    |    |    |    |    |    |    |    |    |    |    |
| 7                    |   | 7           |    | 061                 |    | 03              |            | L           |    | N        |                | X            |    | Z             |    | Z               |    | Z               |    | 0000  |    | Y                    |    | N                |    | N                    |    | V010                   |    |    |    |    |    |    |    |    |    |    |    |    |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

|   |   |                       |
|---|---|-----------------------|
| 1 | 0 | Please See Attachment |
| 1 | 1 |                       |
| 1 | 2 |                       |
| 1 | 3 |                       |
| 1 | 4 |                       |

8 9 FACILITY STATUS 1 5 C 28 29 30 OTHER STATUS NA 31 32 METHOD OF DISCOVERY B Surveillance Test

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z (33) Z (34) AMOUNT OF ACTIVITY (35)

7 8 9 10 11 44

NA LOCATION OF RELEASE (36)

45 80

| PERSONNEL EXPOSURES |   |   |   |      |   |             |    |    |  |
|---------------------|---|---|---|------|---|-------------|----|----|--|
| NUMBER              |   |   |   | TYPE |   | DESCRIPTION |    |    |  |
| 1                   | 7 | 0 | 0 | 37   | Z | 38          | NA | 39 |  |

| PERSONNEL INJURIES |   | NUMBER |   | DESCRIPTION |    |
|--------------------|---|--------|---|-------------|----|
| 1                  | 2 | 0      | 0 | 40          | NA |

|   |   | LOSS OF OR DAMAGE TO FACILITY |      | (43) |          |
|---|---|-------------------------------|------|------|----------|
|   |   | TYPE DESCRIPTION              |      |      |          |
| 1 | 9 | Z                             | (42) | NA   | 1114 015 |

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70

PUBLICITY  
ISSUED DESCRIPTION NA 7910090351 NRC USE ONLY

2 0 N 44

NAME OF PREPARER

W. Verne Childs

PHONE \_\_\_\_\_

315-342-3840

NRC USE ONLY

POWER AUTHORITY OF THE STATE OF NEW YORK  
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 79-061/03L-0

Page 1 of 1

During normal startup operations, while conducting F-ST-4E titled "HPCI Sub-system Logic Functional Test" to satisfy the requirements of Technical Specifications Appendix A, Table 3.2-2, it was noted that Switch No. 3 associated with level instrument 02-3-LIS-72D did not properly pick up its follower relay when the state of Switch No. 3 was changed as a part of F-ST-4E.

The other three switches (including the redundant channel) associated with the same parameter were verified operable therefore, the event did not represent any significant hazard to the public health and safety.

Investigation revealed a wiring error had occurred during the installation of a new switch in June, 1979. When the new switch was installed its proper operation was verified utilizing F-ISP-3-2 titled "Reactor Low-Low/Low-Low-Low Water Level." Review of F-ISP-3-2 revealed that the procedure did not require verification of proper switch action by observation of the follower relay associated with the switch. The wiring error was corrected and proper operation demonstrated on the following day.

To preclude events of this nature in the future, F-ISP-3-2 has been revised to require verification of proper operation of the follower relay.

1114 016