

CONTROL BLOCK:

| | | | | | | |
|--|--|--|--|--|--|--|
| | | | | | | |
|--|--|--|--|--|--|--|

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|---|---|---|---|----|----------------|---|---|---|---|---|---|---|---|---|----|--------------|---|---|---|----|-----|----|--|--|---|
| 0 | 1 | N | Y | J | A | F | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5 |
| 7 | 8 | 14 | | | | | | 15 | 25 | | | | | | | | | | 26 | 30 | | | | 57 | CAT | 58 | | | |
| | | LICENSEE CODE | | | | | | | LICENSE NUMBER | | | | | | | | | | | LICENSE TYPE | | | | | | | | | |

CON'T

REPORT SOURCE L 0 5 0 0 0 3 3 3 0 9 0 5 7 9 1 0 0 3 7 9

7 8 60 61 68 69 74 75 80

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Please See Attachment

03 _____

| | |
|---|---|
| 0 | 4 |
|---|---|

| | |
|---|---|
| 0 | 5 |
|---|---|

| | | |
|---|---|--|
| 0 | 6 | |
|---|---|--|

| | |
|---|---|
| 0 | 7 |
|---|---|

| | |
|---|---|
| 0 | 8 |
|---|---|

0 9 7 R

S F 11 0 1.0

A 12 1.1

B 13 1.2

I N S T R U 14 1.3

S 15 1.4

Z 16 1.5

(17) LER RO REPORT NUMBER [EVENT YEAR
 [7][9] [—]
 21 22 23
 SEQUENTIAL REPORT NO. [0][6][2] [—]
 24 25 26 27
 OCCURRENCE CODE [0][3] [—]
 28 29 30
 REPORT TYPE [L] [—]
 31
 REVISION NO. [0]
 32

ACTION TAKEN 33 [E] 34 (18) Z 35 (19) FUTURE ACTION

EFFECT ON PLANT 35 [Z] 36 (20) SHUTDOWN METHOD

SHUTDOWN METHOD 36 [Z] 37 (21) HOURS 37 [0] 38 [0] 39 [0] 40 [0]

ATTACHMENT SUBMITTED 41 [Y] 42 (23) NPRD-4 FORM SUB. 42 [N] 43 (24) PRIME COMP. SUPPLIER 43 [N] 44 (25) COMPONENT MANUFACTURER 44 [Y] 45 [0] 46 [1] 47 [0]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

| | | |
|---|---|-----------------------|
| 1 | 0 | Please See Attachment |
|---|---|-----------------------|

| | | |
|---|---|--|
| 1 | 1 | |
|---|---|--|

112

| | |
|---|---|
| 1 | 3 |
|---|---|

| | |
|---|---|
| 1 | 4 |
|---|---|

7 8 9 80

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) 002 (29) NA (30) METHOD OF DISCOVERY (31) B (32) Surveillance Test

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

| | | | | | | | |
|---|---|---|----|---|----|----|----|
| 1 | 6 | 2 | 33 | 2 | 34 | NA | NA |
|---|---|---|----|---|----|----|----|

| PERSONNEL EXPOSURES | | NUMBER | | TYPE | | DESCRIPTION | |
|---------------------|---|--------|---|------|----|-------------|-------|
| 1 | 7 | 0 | 0 | 0 | 37 | Z | 38 NA |

| 7 | 8 | 9 | 11 | 12 | 13 | 80 |
|--------------------|---|---|------------------|----|----|----|
| PERSONNEL INJURIES | | | | | | |
| NUMBER | | | DESCRIPTION (41) | | | |

| | | | | | | |
|---|---|---|---|---|----|----|
| 1 | 8 | 0 | 0 | 0 | 40 | NA |
|---|---|---|---|---|----|----|

| LOSS OF OR DAMAGE TO FACILITY | | (43) | 7910090456 | 80 |
|-------------------------------|-------------|------|------------|----|
| TYPE | DESCRIPTION | | | |
| 1-1 | | | | |

| | | | | |
|---|---|---|------|----|
| 7 | 9 | Z | (42) | NA |
|---|---|---|------|----|

PUBLICITY (45)
 ISSUED (44) DESCRIPTION
 NA 1114 232 NRC USE ONLY

[illegible]

NAME OF PREPARER W. Verne Childs

PHONE: 315-342-3840

917-926

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 79-062/03L-0

Page 1 of 1

During normal startup, while conducting F-ST-4E titled "HPCI Sub-system Logic Functional Test" to satisfy the requirements of Technical Specifications Appendix A, Table 3-2.2, it was noted that a plug in instrument 02-3-LIS-72A was leaking. The other instruments monitoring the same parameter were verified operable (See LER-79-061/03L-0) before any attempt to repair the leaking plug was made. Since the other instruments were operable the event did not represent any significant hazard to the public health and safety.

In order to repair the instrument it was placed out of service and a jumper was installed to place it in the trip condition until the plug had been removed and the adjustment screw beneath the plug had been tightened and the plug replaced. This repair was completed on the same day as the discovery.

1114 233