

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M D C C N 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38
CON'T
0 1 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 1100 on October 4, 1979, #11 Component Cooling Heat Exchanger was
0 3 removed from service to perform corrective maintenance on the operator
0 4 for the Heat Exchanger Saltwater outlet valve (1-CV-5206). The problem
0 5 with the operator was corrected and the Heat Exchanger was returned
0 6 to operation at 1455, October 4, 1979. (T.S. 3.7.3.1). This is not a
0 7 repetitive occurrence.

0 8
0 9
SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 14 VALVE SUBCODE 15
V B 11 X 12 X 13 I N S T R U 14 C 15 Z 16
EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 28 29 REPORT TYPE 30 31 REVISION NO. 32
17 7 9 10 5 8 1 0 3 L 1
ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 38 ATTACHMENT SUBMITTED 41 NPD-4 FORM SUB. 42 PRIME COMP. SUPPLIER 43 COMPONENT MANUFACTURER 44
E 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 Y 24 A 25 F 1 3 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Valve 1-CV-5206 would not open until a 20% open electrical signal was
1 1 generated from its controller. This was due to its faulty current to
1 2 pneumatic converter. The converter was recalibrated and valve position
1 3 switches were adjusted. The valve had been operational from a safety
1 4 override standpoint. No preventive action is deemed necessary.

1 5 FACILITY STATUS 28 29 0 8 5 29 N/A 30 METHOD OF DISCOVERY 31 32 Operator Observation
ACTIVITY CONTENT 33 34 35 36 LOCATION OF RELEASE 36
1 6 Z 33 Z 34 N/A 35 N/A 36
PERSONNEL EXPOSURES 37 38 39
1 7 0 0 0 37 Z 38 N/A 39
PERSONNEL INJURIES 40 41
1 8 0 0 0 40 N/A 41
LOSS OF OR DAMAGE TO FACILITY 42 43
1 9 Z 42 N/A 43
PUBLICITY 44 45
2 0 Z 44 N/A 45
7911180 320
NRC USE ONLY

NAME OF PREPARER R. Heibel/P. Rizzo

PHONE: (301) 234-7943/7996