

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	2	1	7	1	0	2	7	7	9	8	1	1	1	3	7	9	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal plant operation, secondary containment was momentarily violated when
0 3 personnel simultaneously opened the reactor building to radwaste building airlock
0 4 doors. This event occurred again 10-31-79 when personnel simultaneously opened the
0 5 reactor building to turbine building airlock doors. Secondary containment integrity
0 6 was demonstrated per HNP-1-3653 Standby Gas Treatment System Operability Section "G",
0 7 to comply with Technical Specification 4.7.C.2. This is a repetitive occurrence; see
0 8 LER 79-68 and LER 79-74. There were no effects on public health or safety.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
		S	A	B		A		Z	Z	Z	Z	Z		Z	
17 LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
21		22		23		24		25		26		27		28	
7		9		—		0		8		6		/		0	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39		40	
F		F		Z		Z		0		N		N		Z	
18		19		20		21		22		23		24		25	
33		34		35		36		37		38		39			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event was design deficiency. The doors were opened simultaneously.

1 1 The present design of the interlock system will not prevent this. A review of the

1 2 present airlock interlocking scheme is under review as stated in LER 79-68 and LER

1 3 79-74.

1 4

7 8 9 80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	0	9	3	29	A	31
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	N/A	35	N/A	36
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	N/A	
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40			N/A	1372 347
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42			N/A		7911200587	
PUBLICITY		ISSUED		DESCRIPTION					
2	0	N	44			N/A			

NAME OF PREPARER S. X. Baxley, Supt. of Operations

PHONE: 912-367-7781