

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0	1	L	6	0	5	0	-	0	3	2	5	7	1	0	2	5	7	9	8	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing PT 9.2, HPCI System Component Test, the control operator noticed

0 3 that the HPCI injection valve F006 could not be operated from the RTGB.

0 4

0 5

0 6

0 7

0 8

Technical Specification 3.5.1, 6.9.1.9b

80

0	9	S	F	11	E	12	B	13	V	A	L	V	O	P	14	B	15	Z	16	7	9	0	8	8	0	3	L	0	0	0	0	Y	23	Y	24	N	25	L	2	0	0	0	26
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	---	---	---	---	---	---	---	----	---	----	---	----	---	---	---	---	---	----

7 8 9 10 11 12 13 18 19 20 21 22 23 24 26 27 28 29 30 31 32 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 An investigation of the valve operator determined that lockwire was missing from

1 1 the drive gear with resultant loosening of the set screw which allowed the drive

1 2 gear key to come out of its keyway. The operator was reassembled correctly and

1 3 tested. No reason could be determined for the missing lockwire. (Cont'd)

1 4

1	5	E	28	0	5	0	29	N/A	B	31	Periodic Test	32	N/A	36
---	---	---	----	---	---	---	----	-----	---	----	---------------	----	-----	----

7 8 9 10 11 12 13 14 44 45 46 80

1	6	Z	33	Z	34	N/A	35	N/A	36
---	---	---	----	---	----	-----	----	-----	----

7 8 9 10 11 12 13 14 44 45 46 80

1	7	0	0	0	37	Z	38	N/A	39	1391 310
---	---	---	---	---	----	---	----	-----	----	----------

7 8 9 10 11 12 13 14 44 45 46 80

1	8	0	0	0	40	N/A	41	N/A	42	POOR ORIGINAL
---	---	---	---	---	----	-----	----	-----	----	---------------

7 8 9 10 11 12 13 14 44 45 46 80

1	9	Z	42	N/A	43	N/A	44	N/A	45	7911280 216
---	---	---	----	-----	----	-----	----	-----	----	-------------

7 8 9 10 11 12 13 14 44 45 46 80

2	0	N	44	N/A	45	N/A	46	N/A	47	N/A
---	---	---	----	-----	----	-----	----	-----	----	-----

7 8 9 10 11 12 13 14 44 45 46 80

NAME OF PREPARER

A. C. Tollison, Jr.

PHONE

919-457-9521

LER CONTINUATION -- RO# 1-79-88

Facility: BSEP Unit No. 1

Event Date: 10-25-79

There is no record of previous corrective maintenance on this operator. The maintenance instruction covering reassembly of the subject components was recently revised providing detailed instructions on reassembly. This is considered an isolated event.

1391 311