

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE L (6) 0 5 0 0 0 2 9 8 (7) 1 0 1 2 7 9 (8) 1 1 0 9 7 9 (9)

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During normal operation, a routine tour of the plant indicated a through-wall crack of a weld in the REC supply to the south critical loop, upstream of the supply isolation valve. This portion is isolatable from the critical loop. The redundant REC loop and Service Water supply were available to supply this critical loop. If the weld failed completely, it would be detectable. Reference LER Report No. 78-27 for an event of similar nature. This event presented no adverse consequences from the standpoint of public health and safety.

SYSTEM CODE S B 11		CAUSE CODE E 12		CAUSE SUBCODE X 13		COMPONENT CODE X X X X X X 14		COMP SUBCODE X 15		VALVE SUBCODE Z 16	
EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 2 9 23 24 25 26		OCCURRENCE CODE 0 3 27 28 29		REPORT TYPE L 30 31		REVISION NO. 0 32			
ACTION TAKEN X 18		FUTURE ACTION C 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 38 39 40		ATTACHMENT SUBMITTED N 23 41	
NPRD-4 FORM SUB. 24 42		PRIME COMP. SUPPLIER A 25 43		COMPONENT MANUFACTURER J 0 3 5 26 44 45 46 47							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The component involved is a weld. The failure is a through-wall crack which has sur-  
1 1 faced as a pinhole leak of undeterminable cause. A soft patch has been applied and  
1 2 the weld evaluated acceptable for continued service. During the next shutdown of  
1 3 sufficient duration, the weld will be replaced. An evaluation of a similar failure  
1 4 which was not reportable, will determine the cause. Update report will be submitted.

FACILITY STATUS (28) 096 (29) NA (30)  
 METHOD OF DISCOVERY (31) A (32) Operator Observation  
 ACTIVITY CONTENT RELEASED OF RELEASE (33) 7 (34) 7 (35) NA  
 LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES			
NUMBER		TYPE	DESCRIPTION (39)
1	7	0000 (37)	Z (38) NA

		PERSONNEL INJURIES		
NUMBER		DESCRIPTION		(41)
1	2	3	4	5
1	0	0	0	NA

POOR ORIGINAL

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72</																																																									

7911270464  
 NRC USE ONLY

NAME OF PREPARER Paul Doan PHONE 402-825-3811

POOR ORIGINAL

1398 184

7911270464

NRC USE ONLY

PHONE: 402-825-3811

## Nebraska Public Power District

COOPER NUCLEAR STATION  
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321  
TELEPHONE (402) 825-3811

CNSS790554

November 5, 1979

Mr. K. V. Seyfrit  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region IV  
611 Ryan Plaza  
Suite 1000  
Arlington, Texas 76011

Dear Sir:

This report is submitted in accordance with Section 6.7.2.B.2 of the Technical Specifications for Cooper Nuclear Station and discusses a reportable occurrence that was discovered on October 8, 1979. A licensee event report form is also enclosed.

Report No.: 50-298-79-28  
Report Date: November 5, 1979  
Occurrence Date: October 8, 1979  
Facility: Cooper Nuclear Station  
Brownville, Nebraska 68321

### Identification of Occurrence:

A condition which lead to operation in a degraded mode permitted by a limiting condition for operation established in Section 3.19.B of the Technical Specifications.

### Conditions Prior to Occurrence:

The reactor was at a steady state power level of approximately 95% of rated thermal power.

### Description of Occurrence:

While inspecting the cable spreading room it was noted that a four inch diameter pipe sleeve in the fire wall between the cable spreading room and the cable expansion room was not properly sealed.

### Designation of Apparent Cause of Occurrence:

Inadequate control of installation of fire seals during a microwave communications system installation in December 1978.

1398 185

Mr. K. V. Seyfrit  
November 5, 1979  
Page 2.


Analysis of Occurrence:

The four inch sleeve, located in the wall between the cable spreading room and the cable expansion room, carries two 1 inch conduits through it. One conduit contains control cable for reactor recirculation motor generator set ventilation flow indication. The other conduit contains cable for microwave communication. The space inside the four inch sleeve and outside of the two one inch conduits was not adequately sealed. The possibility of a fire starting in this area is minimal because no combustible material was present. The cable spreading room is equipped with an automatic sprinkler system which could extinguish a fire if one started. The possibility of a fire spreading through the unsealed sleeve was remote because the sleeve contained no combustible material. This occurrence presented no adverse effect to public health and safety.

Corrective Action:

The four inch sleeve was immediately sealed and an adequate fire barrier established. All remaining sleeves in this area were inspected and verified to be properly sealed. The Technical Specifications also require that the penetrations in the cable spreading room be inspected every 18 months. This event was discussed with the appropriate personnel.

Sincerely,



L. C. Lessor  
Station Superintendent  
Cooper Nuclear Station

LCL:cg  
Attach.

1398 186

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	9	8	7	1	0	0	8	7	9	8	1	1	0	5	7	9	9
60	61									68	69					74		75						80
DOCKET NUMBER											EVENT DATE						REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During inspection of cable spreading room it was noted that one 4 inch pipe sleeve

0 3 in the wall between cable spreading room and cable expansion room was not sealed

0 4 T.S. 3.19.B. The possibility of a fire in this area is minimal because no combus-

0 5 tible material was present. Cable spreading room is equipped with an automatic

0 6 sprinkler system. No significant occurrence took place. This event had no effect

0 7 upon public health and safety. This event is not repetitive.

0 8																				90			
7 8 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE							
0 9		A B (11)		A (12)		E (13)		Z Z Z Z Z Z (14)						Z (15)		Z (16)							
7 8 9		9 10		11		12		13 14 15 16 17 18						19		20							
		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.													
(17) LER-RO REPORT NUMBER		7 9		0 2 8		0 3		L		0													
21		22		23		24		25		26		27		28		29		30		31		32	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
B (18)		H (19)		Z (20)		Z (21)		0 0 0 0 (22)		N (23)		(24)		Z (25)		Z 9 9 9 (26)							
33		34		35		36		37		41		42		43		44		47					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Four inch sleeve in the wall has apparently been unsealed since December 1978.

1 1 | The sleeve was immediately sealed. All other sleeves in this area were also in-

1 2 | spected and verified to be properly sealed. The incident was discussed with ap-

1 3 | propriate personnel.

1	4																													80																										
7	8																													80																										
FACILITY STATUS				POWER				OTHER STATUS (30)																METHOD OF DISCOVERY																DISCOVERY DESCRIPTION (32)																80
1	5	E	(28)	0	9	5	(29)	NA																B	(31)	Shift Supervisor Observation																												80		
7	8																													80																										
ACTIVITY CONTENT				RELEASED OF RELEASE				AMOUNT OF ACTIVITY (35)																LOCATION OF RELEASE (36)																80																
1	6	Z	(33)	Z	(34)	NA																NA																80																		
7	8																													80																										

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA	(39)			

PERSONNEL INJURIES  
NUMBER DESCRIPTION (41)  
1 0000 (40) NA

GOOD ORIGINAL

1 9 2 (42) NA 43

1598 107

PRIORITY		DESCRIPTION		NRC USE ONLY	
2	0	N	NA		

NAME OF PREPARER Ladislav F. Bednar

PHONE 402-825-3811

~~POOR ORIGINAL~~

~~1398-187~~

NRC USE ONLY