

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION.)

0 1 G A E I H 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 6 7 1 1 1 3 7 9 8 1 1 2 8 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 While performing surveillance procedure HNP-2-3504, APRM Instrument Functional Test
0 3 and Calibration, it was found that APRM "F" went inop with 9 LPRM inputs instead of
0 4 10 inputs. No Tech Spec requirements were performed because only 2 channels are
0 5 required per trip channel. B & D channels were still operable. The health and
0 6 safety of the general public was not affected. This is a non-repetitive event.
0 7
0 8

0 9 SYSTEM CODE I D 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE Y 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 7 9 EVENT YEAR 1 1 9 SEQUENTIAL REPORT NO. 0 3 OCCURRENCE CODE L 31 REVISION NO. 0
ACTION TAKEN E 18 FUTURE ACTION E 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER G 0 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 The cause for APRM "F" becoming inop with 9 LPRM inputs instead of 10 inputs was due
1 1 to setpoint drift. Calibration was performed and problem was corrected.
1 2
1 3
1 4

1 5 FACILITY STATUS E 28 % POWER 0 9 4 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION During functional test and calibration 32
1 6 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
2 0 PUBLICITY N 44 DESCRIPTION NA 45

7912050 445

1494 265