

CONTROL BLOCK: L

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 G A E I H 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

1 REPORT SOURCE L 6 0 5 0 0 0 0 3 6 6 7 1 1 1 1 2 7 8 8 1 1 1 2 7 7 8 9
80 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 With the reactor in the Run mode, while performing procedure HNP-2-5202 on
3 2B21-N017B, the instrument was found to be out of tolerance. (Technical Specification
4 3.3.2, Table 33.2-1). The acceptable tolerance range is plus or minus 0.3 inches of
5 the 60 inch range. The other channel was operable and there were no effects to
6 public health and safety.

8 9
9 SYSTEM CODE 1 A 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE INSTRU 14 COMP SUBCODE E 15 VALVE SUBCODE Z 16
17 LER NO REPORT NUMBER 7 8 21 22 SEQUENTIAL REPORT NO. 0 6 7 24 25 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO 0 32
ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 22 ATTACHMENT SUBMITTED N 23 NRC-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER G 0 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 The instrument was out of tolerance due to the setpoint drifting by as much as 8
1 inches. When the instrument could not be calibrated correctly, it was replaced and
2 procedure HNP-2-5202 performed satisfactorily.

8 9
5 FACILITY STATUS B 28 % POWER 0 3 9 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION During surveillance 32
ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
PUBLICATION ISSUED N 44 DESCRIPTION NA 45
7907110 407
349 175
NRC USE ONLY

NAME OF PREPARER R. T. Nix

PHONE (912) 367-7781