

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	
L		C		N		2		0		0		-		0		0		0		3		4		1		1	
L		C		N		2		0		0		-		0		0		0		3		4		1		1	

L

CON'T

REPORT

SOURCE

60

61

DOCKET NUMBER

68

69

EVENT DATE

74

75

REPORT DATE

80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation the Control Room Operator discovered the containment

0 3 | atmosphere particulate monitor failed low at 0850 and again at 0100 on 6/16/79.

0 4 | Following corrective action the monitor was returned to service at 1630 on 6/15/79.

0 5 | and again at 0945 on 6/19/79. The containment atmosphere gaseous radioactivity

0 6 | monitoring system and containment sump alarm system remained operable throughout

0 7 | these events. This is not a repetitive occurrence.

0 8 |

0	9	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50																	
B		B		E		A		I		N		S		T		R		U		E		Z		0		1		0		2		1		0		3		L		0		0		0		0		Y		M		A		W		1		2		0	
B		B		E		A		I		N		S		T		R		U		E		Z		0		1		0		2		1		0		3		L		0		0		0		0		Y		M		A		W		1		2		0	

LER/RO  
REPORT  
NUMBEREVENT YEAR  
7 9CAUSE  
CODECAUSE  
SUBCODESEQUENTIAL  
REPORT NO.OCCURRENCE  
CODEREPORT  
TYPEREVISION  
NO.ACTION  
TAKENFUTURE  
ACTIONEFFECT  
ON PLANTSHUTDOWN  
METHOD

HOURS

ATTACHMENT  
SUBMITTEDNPRD-4  
FORM SUB.PRIME COMP  
SUPPLIERCOMPONENT  
MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | See attached.

1 1 |

1 2 |

1 3 |

1 4 |

1	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50			
E		0		9		9		NA		A		Operator observation		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	
E		0		9		9		NA		A		Operator observation		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	

1	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50						
Z		0		0		0		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	
Z		0		0		0		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	

1	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50							
0		0		0		Z		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	
0		0		0		Z		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	

1	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50								
0		0		0		Z		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	
0		0		0		Z		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	

1	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50											
Z		0		0		0		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	
Z		0		0		0		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA			

2	0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50				
Z		0		0		0		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA	
Z		0		0		0		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA		NA			

NAME OF PREPARER J. S. Lagiewski/M. J. Miernicki

PHONE (301) 234-7942/7962

79072004095

366 018

NRC USE ONLY

LER 79-21/3L  
DOCKET NO. 50-318  
EVENT DATE 6-15-79  
REPORT DATE 7-13-79  
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

It was discovered that the detector pig contained some moisture probably due to a steam leak near the sensing line. The containment sample point was shifted, the pig was dried out, and the monitor was returned to service. Shortly thereafter, the detector tube failed, possibly as a result of the moisture damage. A new detector tube was installed and the monitor again returned to service. The steam leak is scheduled to be repaired during the next few weeks, although the shift in the detector sampling point seems to have solved the moisture problem. (Westinghouse Model 1345 P/N 2372A80-H01).