

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C B E P 1 200-000000-000 341111 4 5

CON'T 01 REPORT SOURCE L 6050-0325 7060279 8071879 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 While performing an inspection of pipe supports and hangers in accordance with IE
03 Bulletin 79-07, the following snubbers were found inoperable: 1) 1G41-12SS98, RHR
04 discharge to fuel pool cooling; 2) 1E21-2SS31, Core Spray line to vessel;
05 3) 1B21-44SS138, vessel head vent; 4) 1E11-90SS275, vessel head spray;
06 5) 1PSN-D3SS71, main steam line "D"; 6) 1G41-12SS33, fuel pool cooling.
07 (Technical Specification 3.7.5, 6.9.1.9.b)

08 09

SYSTEM CODE S H 11 CAUSE CODE X 12 CAUSE SUBCODE X 13 COMPONENT CODE S U P P O R T 14 COMP. SUBCODE D 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 79 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN X 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER B209 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 1E21-2SS31 and 1G41-12SS33 had loose bolts in the clamps. These snubbers were aligned
11 and the bolts tightened per procedure. The other four snubbers had a low fluid level
12 due to leaking seals. These snubbers were rebuilt, functionally tested, and returned
13 to service. Snubber inspections will continue per Technical Specifications.

14 15 16 17 18 19

FACILITY STATUS G 28 % POWER 000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION Hanger Inspection 32

ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE BA 36

PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY ISSUED N 44 DESCRIPTION NA 45

7907210320

413 112

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521