

# LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 G A E I I H 2 0 0 - 1 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 1 1  
4 9 LICENSEE CODE 14 19 LICENSE NUMBER 23 26 LICENSE TYPE 30 37 CAT 38

1 L 6 0 5 0 0 0 3 6 6 7 0 5 1 2 4 7 9 8 0 1 7 1 0 7 9 3  
8 REPORT SOURCE 60 61 DOCKET NUMBER 64 65 EVENT DATE 74 75 REPORT DATE 83

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 While performing HNP-2-3183, Service Water valve operability, 2P41-F315 was closed but  
3 would not reopen electrically. The Reactor Bldg. tripped on high condenser pressure  
4 due to the lack of cooling. The drywell internal pressure increased to > .75 PSIG.  
5 Due to the lack of cooling to the drywell ventilation from Reactor Bldg. chillers.  
6 Per Tech. Specs. 3.6.1.6 primary containment internal pressure shall not exceed 0.75  
7 psig. There were no effects upon Public Health or Safety.

0 3 8 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
9 W A 11 E 12 A 13 V A L V I O P 14 A 15 Z 16  
17 LER NO. REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32  
A 18 Z 19 Z 20 0 0 0 0 0 0 1 0 1 3 L 0  
33 ACTION TAKEN 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUTDOWN METHOD 37 HOURS 38 ATTACHMENT SUBMITTED 39 N° FO. 40 PRIME COMP. SUPPLIER 41 42 COMPONENT MANUFACTURER 43 44 45 46 47  
A 18 Z 19 Z 20 0 0 0 0 0 0 1 0 1 3 L 0 L 2 0 0 0 26

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The limit torque switch, SMB-000, for valve 2P41-F315A had corroded to the switch shaft  
11 and caused the switch to hang after the valve was closed not allowing the valve to  
12 open. Reopened valve by hand, restarted Reactor Bldg. chiller, recovered drywell press.  
13 to less than .75 PSIG within time allowable per Tech. Specs. 3.6.1.6 action statement  
14 and had Troque switch repaired per M.R. 2-79-3181 and functional test of valve cont'd

15 FACILITY STATUS 23 24 % POWER 25 26 OTHER STATUS 30 31 METHOD OF DISCOVERY 32 33 DISCOVERY DESCRIPTION 34 35  
E 23 0 0 9 20 NA A 31 Operator Observation

16 ACTIVITY CONTENT RELEASED OF RELEASE 32 33 AMOUNT OF ACTIVITY 35 36 LOCATION OF RELEASE 39 40  
Z 32 Z 33 NA

17 PERSONNEL EXPOSURES NUMBER 37 38 TYPE 39 40 DESCRIPTION 41 42  
0 0 0 37 Z 38 NA

18 PERSONNEL INJURIES NUMBER 41 42 DESCRIPTION 43 44  
0 0 0 41 NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE 43 44 DESCRIPTION 45 46  
Z 43 NA

20 PRIORITY 47 48  
N 47 NA

79072 30482

NRC USE ONLY

(912) 367-7701

July 12, 1979  
Page 2 (cont'd)

Cause Description and Corrective Action

2P41-F315A was satisfactory. Reference previous  
LER's 2-78-33, 2-78-44 and 2-79-54.

442 006