

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 NYJAFI 200-000-000 341111 4 5
7 8 9 14 15 25 26 30 57 CAT 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CONT

01 L 605000333 7062779 8072379 9
7 8 60 61 68 69 74 75 80
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Please See Attachment
03
04
05
06
07
08

09 CF 11 E 12 B 13 CKTBKR 14 E 15 Z 16
7 8 9 10 11 12 13 18 19 20
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
17 79 039 03 L 0
21 22 23 24 26 27 28 29 30 31 32
 LER RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
A18 Z19 Z20 Z21 0000 Y23 Y24 A25 L2000 26
33 34 35 36 37 40 41 42 43 44 47
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Please See Attachment
11
12
13
14

15 G28 000 29 NA 30 B31 Surveillance Test 32
7 8 9 10 12 13 44 45 46 80
 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
16 Z33 Z34 NA 35 NA 36
7 8 9 10 11 44 45 80
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
17 000 Z37 Z38 NA 39
7 8 9 11 12 13 80
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
18 000 40 NA 41
7 8 9 11 12 80
 PERSONNEL INJURIES NUMBER DESCRIPTION
19 Z42 NA 43
7 8 9 10 80
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
20 N44 NA 45
7 8 9 10 80
 PUBLICITY ISSUED DESCRIPTION
 NAME OF PREPARER W. Verne Childs PHONE: 315-342-3440

7907260652

413 260

NRC USE ONLY

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 79-039/03L-0

Page 1 of 1

While in a cold shutdown condition, during the conduct of Operations Surveillance Test F-ST-35A titled "Containment Cooling Subsystem Logic Functional Test," the "B" loop LPCI injection valve (10-MOV-25B) did not open in response to an automatic open signal. The testing was being conducted to satisfy the requirements of Technical Specifications Appendix A, Table 4.2-2. The other RHR loop and injection valves, as well as both core spray systems, were operational therefore the event did not represent a significant hazard to the public health and safety.

Investigation revealed failure of the torque switch in the valves motor operator. Following replacement of the torque switch assembly, the valve was tested utilizing F-ST-35A, with satisfactory results.