

telecopied 7-3-79

1 EMAIL



Carolina Power & Light Company

Brunswick Steam Electric Plant

P. O. Box 458

Southport, N. C. 28461

July 3, 1979

FILE: B3516.2

SERIAL: BSEP/79-643

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2
LICENSE NO. DPR-62
DOCKET NO. 50-324
CONFIRMATION FACSIMILE FOR AN IMMEDIATELY REPORTABLE EVENT

Dear Mr. O'Reilly:

This facsimile confirms the verbal conversation between Mr. J. M. Brown and Mr. J. E. Ouzts of your office on July 2, 1979.

During reanalyses of Brunswick Unit No. 2 safety-related piping systems resulting from the requirements of IE Bulletin 79-07, it was determined that two snubber support beams in the RHR steam condensing lines did not have the necessary capability to carry calculated loads under worst case seismic conditions. Since this did not meet FSAR commitments, Carolina Power & Light Company decided to replace the beams before exceeding 113 psig reactor pressure.

Additionally, physical inspection of pipe supports of safety-related piping systems in the Unit No. 2 drywell revealed that a pipe guide on a level instrument reference leg was missing. This guide will be installed prior to startup of Unit No. 2.

Corrective actions are in progress at this time. A Licensee Event Report (sequential report number 52) will be submitted as required by Technical Specification 6.9.1.8.1 within 14 days providing further information on this subject.

Very truly yours,

J. C. Tollison, Jr.
J. C. Tollison, Jr., Manager
Brunswick Steam Electric Plant

REP/jro

cc: H. R. Banks
J. E. Ouzts
D. B. Waters

430 005

790284

①

A002
5 1/0

OFFICIAL COPY

7908020441