

Unit 2

LICENSEE EVENT REPORT

Report No. 2-79-33/1T-0

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 P A P B S 2 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4

1 6 0 5 0 - 0 2 7 7 0 7 1 2 7 9 0 7 2 6 7 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

1 Inspection program performed in response to IE Bulletin 79-02 identified
2 two shell type anchors in one support which failed to torque test prop-
3 erly. These anchors are associated with the emergency cooling water
4 system, which is only used in unusual events such as flood or loss of
5 Conowingo Pond. Likelihood of seismic event occurring coincident with
6 unusual environmental events is considered highly unlikely. Therefore,
7 safety significance is minimal. Similiar occurrence LER 2-79-35/IT.

9 S H 11 B 12 C 13 S U P P O R T 14 B 15 Z 16
17 7 9 0 3 3 0 1 T 0
18 19 20 21 22 23 24 25 26
27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 Two of four shell type anchor bolts were improperly installed. The
2 anchor bolts failing the test were immediately replaced in accordance
3 with test procedure with wedge type anchors and successfully tested.

5 E 78 1 0 0 29 U/3 at 98% D 31 Work on I. E. Bulletin 79-02
6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
51 52 53 54 55 56 57 58 59 60
61 62 63 64 65 66 67 68 69 70
71 72 73 74 75 76 77 78 79 80
81 82 83 84 85 86 87 88 89 90
91 92 93 94 95 96 97 98 99 100

437
339 310

INTEL USE ONLY

7908020469