

CONTROL BLOCK: [][][][][][]()

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
1	5	F	29	0	9	4	29	N/A										B	31	N/A																													
7	8	9	10	11	12	13	14											45	46																														
ACTIVITY CONTENT										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																													
1	5	Z	33	Z	34	N/A										N/A																																	
7	8	9	10	11	12	13	14											45	46																														
PERSONNEL EXPOSURE										DESCRIPTION																																							
1	7	0	0	0	32	Z	38	N/A																																									
7	8	9	10	11	12	13	14																																										
PERSONNEL INJURIES										DESCRIPTION																																							
1	5	0	0	0	40	N/A										309 163																																	
7	8	9	10	11	12	13	14																																										
LOSS OF OR DAMAGE TO FACILITY										DESCRIPTION																																							
1	5	Z	42	N/A										7907090344																																			
7	8	9	10	11	12	13	14																																										
PUBLICITY										DESCRIPTION										NRC USE ONLY																													
1	5	N	41	N/A																																													
7	8	9	10	11	12	13	14																																										

NAME OF PREPARED: T. V. Greene, Supt. Plt. Eng. Serv.

PHONE: 912-367-7781

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Cause Description and Corrective Actions (continued)

At this point the shift engineer directed operators to reinsert the rods several notches and the violation was removed.

To avoid recurrence of this type event in the future, shift engineers have been reinstructed to review all available data on a timely basis while directing reactor maneuvers.