

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A R A N D 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT SB

CON'T
0 1 REPORT SOURCE L 6 0 5 P 0 0 3 6 8 7 0 6 0 7 7 9 8 0 7 0 6 7 9 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 Review revealed the surveillance test required by T.S. 3.6.1.3a

0 3 was not performed within the time limit specified. The

0 4 containment Personnel Hatch seal leakage measurement is

0 5 required at least once per 72 hours when the air lock is

0 6 being used for multiple entries. Similar to LER 50-368/
0 7 79-024. Reportable per T.S. 6.9.1.9.c.

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP CIRCUIT VALVE SURCODE

S D A C Z Z Z Z Z Z Z

LER/RD REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION

E H Z Z 0 0 0 0 N N Z 2 9 9 9

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPFD-4 FORM 11B PRIME COMP SUPPLIER COMPONENT MANIPULATOR

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 21

1 0 The scheduling error was due to the irregularity of testing

1 1 caused by weekends. The surveillance test schedule was

1 2 revised to perform the test every Monday, Wednesday, and

1 3 Friday, exceeding the requirement of T.S. 4.6.1.3a. The

1 4 test was satisfactorily completed on 6/7/79.

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

B 0 0 5 PWR Escalation A NA

ACTIVITY CONTENT Test

RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

Z Z NA NA

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

0 0 0 Z NA

PERSONNEL INJURIES NUMBER DESCRIPTION

0 0 0 NA

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

Z NA

PUBLICITY ISSUED DESCRIPTION

N NA

NHC USE ONLY

NAME OF PREPARER Chris Shively

PHONE 501/968-2519

567 207

7907120.650

9