

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE 414/277/2811

7908010385

ATTACHMENT TO LICENSEE EVENT REPORT NO. 79-006/01T-0

Wisconsin Electric Power Company
Point Beach Nuclear Plant Unit 2
Docket No. 50-301

During repair activities connected with NRC IE Bulletin 79-13 and the replacement of the main feed line reducers and a short length of piping on Unit 2 "A" and "B" steam generators, it was confirmed on July 11, 1979, that the branch connection of the incoming 3" auxiliary feed line at the 16" main feed line was not fabricated per design and Piping Code B31.1 requirements.

Calculations indicate that reinforcement of the branch connection falls below that required by the Code.

It should be noted that approximately eight years of operation, along with a preservice hydrostatic test at 1356 psig and a minimum of one 800 psig leak test per year, have not indicated any problem with the integrity of these branch connections.

During the main feed line repair outage, the two branch connections have been replaced by weldolets to meet Code requirements.

Unit 1 auxiliary feed line connections were found to have been similarly constructed and will be reinforced to meet design requirements. This repair will be completed as early as practicable following the return to service of Unit 2.

457 205