

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
1		A		L		B		R		F		1		2		0		0		-		0		0		0		0		-		0		0		3		4		1		1		1		1		4						5																																							
LICENSEE CODE														LICENSE NUMBER																LICENSE TYPE										CAT																																																					

CON'T

0	1	REF. SOURCE	L	6	0	5	0	0	0	2	5	9	7	0	6	2	8	7	9	8	0	7	2	7	7	9	9
7	8		60	61								68	69						74	75						80	
			DOCKET NUMBER										EVENT DATE										REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation while performing SI 4.1.A-8, scram discharge level switch,
0 3 | LS-85-45B, was found failed in the unsafe direction (T. S. table 3.1.A). The inoper-
0 4 | able channel was manually tripped in order to allow continued operation. The redun-
0 5 | dant switch was operable. There have been no previous occurrences. There was no
0 6 | hazard to the public health or safety.

0	7		
0	8		

0 9 7 8 I A 9 10 11 E 12 13 E 14 I N S T R U 15 S 16 Z 17 18 19 20

(17) LER/RO REPORT NUMBER

EVENT YEAR	
7	9
21	22

SEQUENTIAL REPORT NO.		
0	1	1
24	25	26

OCCURRENCE CODE	
0	3
28	29

REPORT TYPE	
L	
30	31

REVISION	
0	
32	33

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
X	18	G	19	Z	20	Z	21	0	0	0	22	Y	23	N	24	N	25	R	2	9	0
33		34		35		36		37				41		42		43		44			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The model SL-305-EI-X was found to have a buildup of foreign material in the pivot pin

1 1 area which prevented movement of the switch actuator rod. The switch was cleaned,

1 2 recalibrated, and functionally tested. A procedure will be developed to periodical

1 3 flush the switches.

1 4 7 8 9 80

FACILITY STATUS (28) 1 5 E 7 8 9

% POWER (29) 0 9 5 10 12

OTHER STATUS (30) NA 13 44

METHOD OF DISCOVERY (31) E 45 46

DISCOVERY DESCRIPTION (32) Surveillance Testing 80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 34 NA

7 8 9 10 11 44

AMOUNT OF ACTIVITY (35)

NA

45 80

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	000	Z
7	8	9	11
12	13	14	15
16	17	18	19
20	21	22	23
24	25	26	27
28	29	30	31
32	33	34	35
36	37	38	39
40	41	42	43
44	45	46	47
48	49	50	51
52	53	54	55
56	57	58	59
60	61	62	63
64	65	66	67
68	69	70	71
72	73	74	75
76	77	78	79
80	81	82	83
84	85	86	87
88	89	90	91
92	93	94	95
96	97	98	99

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	40	NA

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) NA 7908010 552 J

PUBLICITY

ISSUED DESCRIPTION NA

NRC USE ONLY

NAME OF PREPARER _____

PHONE: 4-99-744

462 344

100