

LICENSEE EVENT REPORT

CONTROLLER BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 OHDBS1200-00NPF-0334111145
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

01 REPORT SOURCE L6050-0346707087980802799
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On July 8, 1979, during a checkout of a relay in the motor operator control circuit of
03 valve MS-106, "Main Steam Inlet to Auxiliary Feed Pump Turbine 1-1 Isolation Valve",
04 torqued out while opening. The valve was declared inoperable at 1530 hours, placing
05 the unit in the action statement of Technical Specification 3.7.1.2. There was no
06 danger to the health and safety of the public or station personnel. The unit had been
07 shutdown since March 31, 1979. Auxiliary Feedwater (AFW) Train 1-2 was operable through-
08 out this occurrence. (NP-33-79-85)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

09 SYSTEM CODE CH11 CAUSE CODE E12 CAUSE SUBCODE A13 COMPONENT CODE VALVOP14 COMP. SUBCODE A15 VALVE SUBCODE Z16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17 LER/RO REPORT NUMBER 7923 SEQUENTIAL REPORT NO. 073 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0
ACTION TAKEN E18 FUTURE ACTION X19 EFFECT ON PLANT Z20 SHUTDOWN METHOD Z21 HOURS 000 ATTACHMENT Y23 NPR-4 FORM SUB. Y24 PRIME COMP. SUPPLIER A25 COMPONENT MANUFACTURER L2000
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The apparent cause is believed to be normal wear of the valve internal parts which
11 necessitated slight adjustment of the torque switch setting. The torque switch
12 setting and the open limit switch settings were adjusted, and the valve successfully
13 stroked twice against full differential pressure. MS-106 was tested per the AFW Sys-
14 tem Monthly Test and was declared operable on July 10, 1979.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

15 FACILITY STATUS C28 % POWER 000 OTHER STATUS NA30 METHOD OF DISCOVERY A31 DISCOVERY DESCRIPTION Observed during maintenance checkout
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

16 ACTIVITY CONTENT RELEASED OF RELEASE Z33 Z34 NA AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17 PERSONNEL EXPOSURES NUMBER 000 TYPE Z37 DESCRIPTION NA39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

18 PERSONNEL INJURIES NUMBER 000 DESCRIPTION NA41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z42 DESCRIPTION NA43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

20 PUBLICITY ISSUED DESCRIPTION N44 NA45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

7908060455 516 009 NRC USE ONLY
DVR 79-104 John J. O'Neill 419-259-5000, Ext. 293

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-79-85

DATE OF EVENT: July 8, 1979

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Main Steam line to Auxiliary Feed Pump Turbine 1-1 steam inlet isolation val : MS-106 failed to operate properly.

Conditions Prior to Occurrence: The unit was in Mode 3, with Power (MWT) = 0, and Load (Gross MWE) = 0.

Description of Occurrence: On July 8, 1979, during checkout of the relay in the motor operator control circuit of valve MS-106, "Main Steam Inlet to Auxiliary Feed Pump Turbine (AFPT) 1-1 Isolation Valve", MS-106 torqued out while opening and was declared inoperable at 1530 hours. This placed the unit in the Action Statement of Technical Specification 3.7.1.2 which requires two independent Auxiliary Feedwater Trains to be operable in Modes 1, 2, and 3.

Designation of Apparent Cause of Occurrence: The apparent cause of this problem is believed to be due to normal wear of the valve internal parts which made it necessary to increase the torque switch setting slightly.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. The unit had been shutdown since March 31, 1979, and throughout this occurrence. Auxiliary Feedwater Train 2 was operable at the time of this occurrence.

Corrective Action: Under Maintenance Work Order (MWO) 79-2461, the motor operator was removed, inspected and reinstalled. The open torque switch setting was increased from 1.9 to 2.5. The valve was stroked twice and operated properly. However, when operations personnel attempted to stroke the valve, it torqued out while going closed. Maintenance personnel then decreased the open torque switch setting of the valve to 2.4 and made a slight adjustment to the open limit switch in order to keep it closed longer when the valve is moving off its back seat. The valve was stroked twice against full differential pressure and operated properly. MS-106 was then tested per ST 5071.01, "Auxiliary Feedwater System Monthly Test", and was declared operable on July 10, 1979. A Maintenance Work Order has been written to inspect MS-106 internally at the refueling outage.

Failure Data: A previous inoperability of valve MS-106 was reported in Licensee Event Report NP-33-79-03. This previous incident was caused by a dirt buildup on the valve stem.