

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7	Q	1	8							
	A	L	J	M	F	I	14			
<small>LICENSEE CODE</small>										
15	O	O	-	O	O	O	-	O	O	25
<small>LICENSE NUMBER</small>										
	4	1	1	1	1	30				
<small>LICENSE TYPE</small>										
						57 CAT 58				

CON'T

0 1 7 8

REPORT SOURCE L 60

0 5 0 0 0 3 4 8 61 DOCKET NUMBER 68

0 4 0 8 7 8 69 EVENT DATE 74

0 8 0 8 7 9 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 At 2238 on 4/8/78, while changing turbine governor valve control from single
03 to sequential valve control, a DEH malfunction caused a load rejection of
04 approximately 170 MW. This caused a momentary Tavg rise to 582F (per
05 Tave/Tref recorder). T/S 3.2.5 requires Tavg to be maintained less than or
06 equal to 581.2F. The rod control system automatically responded and
07 reduced Tavg to less than 581.2F. This was a momentary transient. The
08 health/safety of the public was not affected.

SYSTEM CODE [A][A] 9 10		CAUSE CODE [E] 11		CAUSE SUBCODE [G] 12		COMPONENT CODE [X][X][X][X] 13 14 15 16				COMP. SUBCODE [Z] 19		VALVE SUBCODE [Z] 20	
LER/RO REPORT NUMBER [7][8] 21 22		EVENT YEAR [7][8] 21 22		SEQUENTIAL REPORT NO. [0][2][4] 24 25 26		OCCURRENCE CODE [0][3] 28 29		REPORT TYPE [L] 30		REVISION NO. [1] 32			
ACTION TAKEN [X] 33		FUTURE ACTION [Z] 34		EFFECT ON PLANT [Z] 35		SHUTDOWN METHOD [Z] 36		HOURS [0][0][0][0] 37 38 39 40		ATTACHMENT SUBMITTED [Y] 41		NPRD-4 FORM SUB. [Y] 42	
PRIME COMP. SUPPLIER [N] 43		COMPONENT MANUFACTURER [W][1][2][0] 44 45 46 47											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 Load rejection due to DEH malfunction resulted in momentary increase in
11 Tavg. The control rods were automatically stepped in and Tavg was reduced.
12 A Westinghouse field engineer has been onsite and identified several
13 problems contributing to the load rejection. These problems have been
14 resolved.

8 9 FACILITY STATUS 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 5 E 0 9 2 NA A NA

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 7 8 9 10 11

AMOUNT OF ACTIVITY

NA

LOCATION OF RELEASE

NA

PERSONNEL EXPOSURES			
NUMBER		TYPE	DESCRIPTION
1	7	0 0 0	Z NA

PERSONNEL INJURIES		80
NUMBER		DESCRIPTION
1	8	0 0 0 NA

8 9		11 12		80
TYPE		LOSS OF OR DAMAGE TO FACILITY		
		DESCRIPTION		
1	9		NA	

8 9		PUBLICITY										NRC USE ONLY									
ISSUED		DESCRIPTION																			
2 0		NA																			
7 8		9										10									

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156

628 132

7908140 745 S

ALABAMA POWER COMPANY
JOSEPH M. FARLEY NUCLEAR PLANT
DOCKET NO. 50-348
ATTACHMENT TO LER 78-024/03L-1

Facility: Joseph M. Farley Unit 1

Report Date: 8/8/79

Event Date: 4/8/78

Identification of Event:

Load rejection due to DEH malfunction resulted in momentary increase in Tav_g.

Conditions Prior to Event:

The plant was in mode 1 operating at 92% power. The turbine governor valve control was in single valve control.

Description of Event:

At 2238 on 4/8/78, while changing turbine governor valve control from single valve to sequential valve control, a DEH malfunction caused a load rejection of approximately 170 MW. This caused a momentary Tav_g rise to 582°F (per Tav_g/Tref. recorder). T/S 3.2.5 requires Tav_g to be maintained less than or equal to 581.2°F. The rod control system automatically responded and reduced Tav_g to less than 581.2°F. This was a momentary transient.

Designation of Apparent Cause:

A Westinghouse field engineer identified the following problems which contributed to the load rejection when changing turbine governor valve control from single valve to sequential valve control:

1. The governor valves were remaining 5% open due to the setting on GV close deadband.
2. Impulse and megawatt loops rejecting and severe load oscillations were attributed to a faulty AM card.
3. No. 3 governor valve was operating erratically due to a faulty servo-card. No. 4 governor valve had been isolated and may have contributed to the erratic operation of No. 3 governor valve.

Analysis of Event:

Tav_g was within Technical Specification limits at the time of the occurrence. Load rejection due to DEH malfunction resulted in a momentary increase in Tav_g. The control rods automatically stepped in and Tav_g was reduced. The health and safety of the public was not affected.

Effect on Plant:

This occurrence had no significant effect on plant operation.

Corrective Action:

1. The GV close deadband was changed from 5 to 0.
2. The associated AM card was located and replaced.
3. No. 3 governor valve servo card was replaced and No. 4 governor valve has been repaired.

Failure Data:

No previous failures of the DEH, while changing turbine governor valve control from single valve to sequential valve control, have resulted in Tavg problems.