

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L G R P 3 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 - - 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 36

CON'T
01 REPORT SOURCE L G 0 5 0 - 0 3 0 2 0 6 1 1 3 7 9 0 7 0 3 7 9 9
7 8 9 DOCKET NUMBER 39 40 EVENT DATE 44 45 REPORT DATE 49

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 At 1530 (Mode 5) it was determined that SP-179, containment leakage
03 tests B & C, exceeded the due date of 18 November 1978. This created
04 an event contract to Technical Specification 4.6.1.2.d. No effect
05 upon public health and safety as the plant remained in a safe shut-
06 down condition. This is the first occurrence of this type reported.
07
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
Z Z 11 A 12 X 13 Z Z Z Z Z 14 Z 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 LER NO REPORT NUMBER 7 9 1 0 5 9 1 0 1 3 1 L 1 0
21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED APPROX FORMULAS PRIVATE COMP SUPPLIER COMPONENT MANUFACTURER
H 18 Z 19 Z 20 Z 21 0 0 0 0 2 23 Y 24 N 25 Z 26 Z 27 9 9 9 9 2
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The cause of this event is attributed to personnel error. A 25% extension
11 for the completion of the surveillance procedure, was inadvertently applied
12 to the 24 month time interval of SP-179. SP-179 was completed satisfactorily
13 on 19 June 1979. The limitations of surveillance procedures with definite
14 time intervals was discussed with the responsible individual.

15 FACILITY STATUS POWER OTHER STATUS 30 METHOD OF DISCOVERY 32
G 23 0 0 0 29 N/A 44 B 31 Surveillance procedure review
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

16 ACTIVITY CONTENT RELEASED OR RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 29
Z 33 Z 34 NA 44 NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 0 1 2 NA 38
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

18 PERSONNEL INJURIES NUMBER DESCRIPTION 31
0 0 0 0 20 NA 30
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 31
Z 40 NA 30
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

20 PUBLICITY ISSUED DESCRIPTION 35
N 44 NA 30
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER J. Cooper, Jr. PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

7907130367

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-059/03L-0

Facility: Crystal River Unit 3

Report Date: 03 July 1979

Occurrence Date: 13 June 1979

Identification of Occurrence: Failure to perform surveillance procedure SP-179, Containment Leakage Tests B & C, within the required time interval of Technical Specification 4.6.1.2.d.

Conditions Prior to Occurrence: Mode 5 cold shutdown.

Description of Occurrence: At 1530 it was determined that surveillance procedure SP-179, Containment Leakage Tests B & C, had exceeded the due date of 18 November 1978. SP-179 was scheduled and completed with satisfactory results 19 June 1979.

Designation of Apparent Cause: The cause of this event is attributed to personnel error. A 25% extension for completion of the surveillance procedure was inadvertently applied to the 24 month time interval of SP-179.

Analysis of Occurrence: No effect upon public health and safety as the plant remained in a safe shutdown condition.

Corrective Action: The limitations of surveillance procedures with definite time intervals were discussed with the responsible individual.

Failure Data: This is the first occurrence of this type reported.