

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	-	0	3	4	6	7	0	7	1	7	7	9	8	0	8	1	3	7	9	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

At 0120 hours on 7/17/79, Post-Accident Containment Radiation Monitor RE 5029 was taken out of service due to failure of the pump. This placed the unit in the Action Statement of T.S. 3.3.3.6 which requires that two post-accident containment monitoring systems be operable in Modes 1, 2, or 3. There was no danger to the health and safety of the public or station personnel. The other containment post-accident monitor RE 5030 was operable throughout this occurrence. (NP-33-79-95)

0	8	9	SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE		COMP. SUBCODE	VALVE SUBCODE	90
7	8	9	B	B	E	B	P	M	P	X	X
9	10	11	11	12	13	14	15	16	17	18	19
0	9	10	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE	REVISION NO.	20
7	8	9	7	9	0	8	1	0	3	L	0
21	22	23	24	25	26	27	28	29	30	31	32
ACTION TAKEN		FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER		
C	X	Z	Z	0	0	Y	Y	A	V	1	1
18	19	20	21	22	23	24	25	26	27	28	29

1 0 The cause of this occurrence was component failure of the pump bearings caused by a  
1 1 loss of lubrication due to high ambient temperature. The pump was removed, rebuilt,  
1 2 test run, and reinstalled. At 1640 hours on 7/17/79, RE 5029 was declared operable,  
1 3 removing the unit from the Action Statement. Improved pump bearings with high  
1 4 temperature lubricant are to be installed in the near future.

7 8 9  
FACILITY STATUS      % POWER      OTHER STATUS (30)      METHOD OF DISCOVERY      DISCOVERY DESCRIPTION (32)

1 5 E (28)      1 0 0 (29) NA      A (31) Operator observation

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

(1) (6) (Z) (33) NA

2 2 2 10 11 44

LOCATION OF RELEASE (36)

NA

45

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION (39)						
1	2	0	0	0	(37)	2	(38)	NA		

7	8	9	11	12	13
PERSONNEL INJURIES					
NUMBER			DESCRIPTION (41)		

7 8 9 11 12 NA  
LOSS OF OR DAMAGE TO FACILITY (40) 761343

TYPE		DESCRIPTION
1	2	NA

7 8 9 10

7908210460

PUBLICATIONS  
ISSUED DESCRIPTION

20 N 44 NA

NRC USE ONLY

TOLEDO EDISON COMPANY  
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE  
SUPPLEMENTAL INFORMATION FOR LER NP-33-79-95

DATE OF EVENT: July 17, 1979

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Containment Post-Accident Radiation Monitor RE 5029 was inoperable

Conditions Prior to Occurrence: The unit was in Mode 1, with Power (MWT) = 2772, and Load (Gross MWE) = 919

Description of Occurrence: At 0120 hours on July 17, 1979, Post-Accident Radiation Monitor RE 5029 was taken out of service because of pump failure.

This placed the unit in the Action Statement of Technical Specification 3.3.3.6 which requires that two post-accident containment monitoring systems be operable in Modes 1, 2, or 3. The Action Statement requires that the inoperable radiation monitor be returned to service within 30 days or the unit must be placed in Hot Shutdown (Mode 4) within the next 12 hours.

Designation of Apparent Cause of Occurrence: Upon disassembly of the failed pump, it was discovered the failure was caused by the bearing losing lubrication due to high ambient temperature.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. This instrument does not control any equipment but is used for monitoring purposes only. No other systems were affected by this occurrence. No incident requiring use of this instrumentation occurred during the time the monitor was inoperable. The other containment post-accident radiation monitor, RE 5030, was operable during the period that RE 5029 was inoperable.

Corrective Action: Under Maintenance Work Order 79-2519, the pump was removed, rebuilt, test run, and reinstalled. At 1640 hours on July 17, 1979, Section 6.4 of Surveillance Test ST 5032.16, "Radiation Monitor Functional Test" was completed and RE 5029 was declared operable. This removed the unit from the Action Statement of Technical Specification 3.3.3.6.

Improved pump bearings with high temperature rated lubricant are on site. Installation is expected in the near future. Facility Change Request (FCR) 78-521 has been written to reduce pump speed in order to reduce the load on the pump bearings. The necessary materials to complete FCR 78-521 are expected to be delivered by mid-August, 1979.

Failure Data: This is a repetitive failure. Previous pump related problems with the radiation monitors have been reported in Licensee Event Reports NP-33-78-30, NP-33-78-54, NP-33-78-77, NP-33-78-143, NP-33-79-37, and NP-33-79-42.