

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1
 7 8
 REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
 L 5 0 5 0 0 0 3 1 8 7 0 7 1 7 7 9 3 0 3 1 7 7 2 9

EVENT DESCRIPTION: M.D. PROBABLE CONSEQUENCES (10)

[02] During a normal operation periodic water inventory check, the balance indicated
[03] that unidentified reactor coolant leakage was greater than 1 gpm. A containment
[04] inspection revealed leakage from within 21B reactor coolant pump middle seal
[05] pressure transmitter. The transmitter was isolated. This is not a repetitive
[06] event. (This references Technical Specification 3.4.6.2).

SYSTEM CODE C B 11		CAUSE CODE E 12		CAUSE SUBCODE C 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE T 15		VALVE SUBCODE X 16	
LER. NO. REPORT NUMBER 7 8		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 0 2 6		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0	
ACTION TAKEN X 18		FUTURE ACTION A 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23	
NFRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER F 1 2 0 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The transmitter was found to be leaking internally from its element. Immediate
1 1 action was to isolate the transmitter. Due to radiation levels in the area, no
1 2 further action has been taken. The transmitter will be replaced during a future
outage.

7 8 9

FACILITY STATUS			% POWER		OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
1	5	E	1	0	NA	B	Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
1 7	0 0 0 (37)	NA (38)

774265

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
		40	NA

79082305/3⁸⁰

7		8	9	10												80
		PUBLICITY														
ISSUED		DESCRIPTION		(45)												NRC USE ONLY
2	0		(44)	NA												
7	8	9	10											68	69	80

NAME OF PREPARER R. Heibel/P. G. Rizzo

PHONE: (301) 234-7942/7986

0-800-841-070