

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 F L G R P 3 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 - - 5

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

CONT 0 1

REPORT SOURCE L 6 0 5 0 - 0 3 0 2 7 0 7 2 3 7 9 6 0 8 1 4 7 9 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 1630 in Mode 4, it was reported that chloride concentration in the pressurizer was .18ppm. This created an event contrary to Technical Specification

0 3 3.4.7. Redundancy NA. No effect upon the plant or general public as the

0 4 plant remained in a safe shutdown condition. This is the second occurrence

0 5 of this type reported. Reference LER 79-23.

0 6

0 7

0 8

0 9

SYSTEM CODE C G 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z Z 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

17 LER NO 7 9 REPORT NUMBER 21 22

EVENT YEAR 7 9 21 22

SEQUENTIAL REPORT NO. 0 6 7 23 24

OCCURRENCE CODE 0 1 3 25 26

REPORT TYPE L 27 28

REVISION NO 0 29 30

ACTION TAKEN X 18 FUTURE ACTION X 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22

ATTACHMENT SUBMITTED Y 23 APPROVAL N 24 REVIEWER Z 25 COMPONENT MANUFACTURER Z 9 9 9 26

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event is attributed to the concentration of chlorides re-

1 1 sulting from the steaming action in the pressurizer during startup. Pressur-

1 2 izer spray flow was increased diluting chlorides to within specification at

1 3 0600 on 24 July 1979.

1 4

1 5

1 6

1 7

1 8

1 9

2 0

FACILITY STATUS G 23 POWER 0 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 RECOVERY DESCRIPTION Technician observation 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

ACTIVITY CONTENT Z 33 RELEASED OR RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PERSONNEL EXPOSURES NUMBER 0 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PERSONNEL INJURIES NUMBER 0 0 0 0 40 DESCRIPTION NA 41

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PUBLICITY N 44 DESCRIPTION NA 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

NAME OF PREPARED J. Cooper

PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-067/03L-0

Facility: Crystal River Unit #3

Report Date: 14 August 1979

Occurrence Date: 23 July 1979

Identification of Occurrence:

Pressurizer chloride concentration out of specification contrary to Technical Specification 3.4.7.

Conditions Prior to Occurrence:

Mode 4 Hot Shutdown.

Description of Occurrence:

At 1630, it was reported that the chloride concentration in the pressurizer was .18 ppm. This exceeded the Technical Specification steady state limit of .15 ppm. Sampling frequency was increased to two (2) hour intervals. Pressurizer spray flow was increased to dilute the high chloride concentration. Subsequent samples taken and analysed at 0000 on 24 July were corrected for turbidity and were found to contain an actual chloride concentration of .08 ppm. It cannot be accurately determined if the original samples were affected by turbidity, indicating erroneous chloride concentrations. Therefore, the results of the original sample were considered valid.

Designation of Apparent Cause:

The apparent cause of this event is attributed to the concentration of chlorides resulting from the steaming action in the pressurizer during plant startup.

Analysis of Occurrence:

No effect on the plant or general public as the plant remained in a safe shutdown condition.

Corrective Action:

Plant Startup Procedure OP-202 is being revised to implement explicit guidelines for maintaining primary system chemistry control during startup.

Failure Data:

774288

This is the second occurrence of this type reported. Reference LER 79-23.