

September 18, 1979

Mr. James P. O'Reilly, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Serial No. 711A
PSE&C/CGC:mac:wang

Docket No. 50-339

Dear Mr. O'Reilly:


On August 24, 1979, a report was made under the provisions of 10CFR50.55(e) concerning indications found in feedwater lines by radiography required by I.E. Bulletin 79-13. On August 29, 1979, we submitted a five day letter (Serial No. 711) in accordance with the reporting requirements of 10CFR21.

We indicated in our five day letter that 62 welds were radiographed in August. This number should be corrected to 59.

Our five day letter detailed the problem and the corrective action taken for all indications found except weld SW-27 on line 16" WFPD-424-601-Q2. We have now completed ultrasonic examination with longitudinal and shear waves on SW-27; no rejectable indications were found, and no repair work is required. Thus, we have determined that none of the radiographic indications found represents a significant deficiency or a substantial safety hazard.

This is our final report under the provisions of 10CFR50.55(e). If further information is required, please advise.

Very truly yours,


Sam C. Brown, Jr.
Senior Vice President - Power Station
Engineering and Construction

cc: Mr. Victor Stello, Director
Office of Inspection & Enforcement

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation

7909250 445 1021 227