

Unit 2

LICENSEE EVENT REPORT

Report No. 2-79-42/1T

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99

CON'T
REPORT SOURCE: L 0 5 0 - 0 2 7 7 0 9 0 6 7 9 0 9 2 0 7 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 Seismic and redundancy design deficiencies involving electrical feeds
0 3 discovered on CAD system valves and instrumentation. Safety significance
0 4 minimized by the availability of alternate methods of ensuring system
0 5 operability.
0 6
0 7
0 8
0 9

SYSTEM CODE: S E 11
CAUSE CODE: B 12
CAUSE SUBCODE: A 13
COMPONENT CODE: I N S T R U 14
COMP. SUBCODE: P 15
VALVE SUBCODE: Z 16
EVENT YEAR: 7 9
SEQUENTIAL REPORT NO.: 0 4 2
OCCURRENCE CODE: 0 1
REPORT TYPE: T
DIVISION NO.: 0
ACTION TAKEN: F 18
FUTURE ACTION: F 19
EFFECT ON PLANT: Z 20
SHUTDOWN METHOD: Z 21
HOURS: 0 0 0 0
ATTACHMENT SUBMITTED: Y 23
NPRD-4 FORM SUB: N 24
PRIME COMP. SUPPLIER: A 25
COMPONENT MANUFACTURER: X 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 Deficiencies resulted from inadequate design by Architect-Engineer.
1 1 Corrective action in progress to install and relocate the CAD system
1 2 power and control cables.
1 3
2 3

FACILITY STATUS: E 28
POWER: 1 0 0 29
OTHER STATUS: Unit 3 at 86% 30
METHOD OF DISCOVERY: D 31
DISCOVERY DESCRIPTION: Evaluation of system design 32
REASON FOR RELEASE: Z 33
AMOUNT OF ACTIVITY: N/A 35
LOCATION OF RELEASE: N/A 36
PERSONNEL EXPOSURES: 0 0 0 37
PERSONNEL INJURIES: 0 0 0 40
DISC OF OR DAMAGE TO FACILITY: Z 42
TYPE: N/A 43

POOR ORIGINAL

1060 019

7910010435

REASON FOR RELEASE: N 44
NAME OF PREPARED: M. J. Cooney
PHONE: (215) 841-5020