

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M D C C N 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 7 7 0 9 1 4 7 9 3 1 0 0 4 7 9 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 At 2030, while performing a surveillance test, #12 containment spray pump

0 3 tripped on ground overcurrent. The pump was declared inoperable and

0 4 placed out of service per T.S. 3.6.2.1. #12 containment spray pump was

0 5 tested satisfactorily and returned to service at 1655 on 9/17/79. The

0 6 redundant spray pump and containment coolers remained operable during the

0 7 event. This is not a repetitive occurrence.

0 8 9 80

0 9 SYSTEM CODE S B 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE M O T O R X 14 CORR. SUBCODE Z 15 VALVE SUBCODE Z 16

17 LER NO. REPORT NUMBER 18 19 EVENT YEAR 7 9 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0 0 0 0 23 ATTACHMENT SUBMITTED N 24 NRC-4 FORM SUB. Y 25 PRIME COMP. SUPPLIER A 26 COMPONENT MANUFACTURER A 1 8 0 27

28 OCCURRENCE CODE 0 3 29 REPORT TYPE L 30 REVISION NO. 0 31

32 ACTION TAKEN C 33 FUTURE ACTION Z 34 EFFECT ON PLANT Z 35 SHUTDOWN METHOD Z 36 HOURS 0 0 0 0 37 ATTACHMENT SUBMITTED N 38 NRC-4 FORM SUB. Y 39 PRIME COMP. SUPPLIER A 40 COMPONENT MANUFACTURER A 1 8 0 41

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 It appears that one of the motor stator coils had chafed against the incoming

1 1 phase lead, thus developing a short circuit at the coil end, past the coil

1 2 knuckle, and the "B" phase wire. The other containment spray motors will be

1 3 inspected for proper rigidity at the stator coil end-turns.

1 4 9 80

1 5 FACILITY STATUS E 28 POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Operator Observation 32

1 6 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

1 7 PERSONNEL EXPOSURES 0 0 0 38 Z 39 DESCRIPTION NA 40

1 8 PERSONNEL INJURIES 0 0 0 41 DESCRIPTION NA 42

1 9 DAMAGE OR DAMAGE TO FACILITY Z 43 DESCRIPTION NA 44

2 0 FACILITY TYPE 1 41 45

2 1 2 2 23 S. M. Davis/E. P. Bauer (901) 234-7942/7906

POOR ORIGINAL

1076 099

7910110313

NRC USE ONLY