

LICENSEE EVENT REPORT

CONTROL BLOCK.

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4					
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	CLASS		35

CON'T

REPORT SOURCE: 0 1 7 8 L 6 0 5 0 0 0 2 5 9 7 0 9 2 0 7 9 6 1 0 1 8 7 9 6

DOCKET NUMBER: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

REPORT DATE: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, radiation monitor, RM-90-250, was found to be erratic and was
0 3 | out of service for approximately nine and one-half hours contrary to T. S. 3.8.B.8.
0 4 | Temporary monitoring by the chemical lab was established within one hour and continued
0 5 | during this period. There was no hazard to the public health or safety. Previous
0 6 | events: 259/795, 259/796, 260/7820, and 260/7822.
0 7 |
0 8 |

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP SUBCODE		VALVE SUBCODE	
0	9	M	C	E	E	I	N	S	T	R	U
7	8	9	10	11	12	13	14	15	16	17	18
(17) YEAR, MONTH, REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
7	9	7	9	0	2	4	0	3	L	0	
21	22	23	24	25	26	27	28	29	30	31	32
ACTION, RESERVE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUB PRIOR	
X	Z	Z	Z	Z	0	0	0	0	Y	N	L
18	19	20	21	22	23	24	25	26	27	28	29

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

1 0 Moisture had collected in the detector of the model SC-2B, causing the detector fail-
1 1 ure. The detector was replaced. The moisture is caused by various leaks in areas
1 2 being sampled. No recurrence control action is planned.
1 3
1 4

1200 288

POOR ORIGINAL

POOR ORIGINAL

DH-2N3

7910230

LER SUPPLEMENTAL INFORMATION

BFRO-0)- 259 / 7924 Technical Specification Involved 3.8.B-8

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 9/20/79 Time of Occurrence 0045 Unit 1

Identification and Description of Occurrence:

Particulate channel failed and was out of service for approximately 9-1/2 hours.

Conditions Prior to Occurrence:

Unit 1 operating @ 100% power.

Unit 2 @ 90% power.

Unit 3 in refueling outage.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Chemical laboratory established temporary monitoring.

Apparent Cause of Occurrence:

Moisture in sample lines collected in detector.

Analysis of Occurrence

Moisture is caused by various leaks in areas being sampled by the CAM.

Corrective Action:

Replaced detector and functionally tested channel.

1200 289

Failure Data:

259/795, 259/796, 260/7820 and 260/7822.

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision:

POOR ORIGINAL