

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | G | A | E | I | H | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5

8 9 | LICENSEE CODE | 14 15 | LICENSE NUMBER | 25 26 | LICENSE TYPE | 30 31 | CAT | 56 57

CON'T

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 2 | 1 | 7 | 1 | 0 | 0 | 9 | 7 | 9 | 8 | 1 | 0 | 1 | 7 | 7 | 9 | 9

8 9 | REPORT SOURCE | 60 61 | DOCKET NUMBER | 68 69 | EVENT DATE | 74 75 | REPORT DATE | 80 81

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Main Stack flow transmitters, D11-N026A and B, were found to be inop. The pens

0 3 | on the control room recorders, D11-R625, were downscale which eliminated all

0 4 | indications of stack flow. There were no effects on the environs. There have been

0 5 | no previous failures of this type.

0 6 |

0 7 |

0 8 |

7 8 9

0 9 | I | E | 11 | E | 12 | E | 13 | I | N | S | T | R | U | 14 | T | 15 | Z | 16

8 9 | SYSTEM CODE | 11 12 | CAUSE CODE | 12 13 | CAUSE SUBCODE | 13 14 | COMPONENT CODE | 18 19 | COMP. SUBCODE | 19 20 | VALVE SUBCODE | 20 21

17 | LER/RO REPORT NUMBER | 21 22 | EVENT YEAR | 23 24 | SEQUENTIAL REPORT NO. | 25 26 | OCCURRENCE CODE | 27 28 | REPORT TYPE | 29 30 | REVISION NO. | 31 32

18 | X | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | N | 24 | Z | 25 | F | 1 | 2 | 8 | 26

33 34 | ACTION TAKEN | 35 36 | EFFECT ON PLANT | 37 38 | SHUTDOWN METHOD | 39 40 | HOURS | 41 42 | ATTACHMENT SUBMITTED | 43 44 | NRRD-4 FORM SUB. | 45 46 | PRIME COMP. SUPPLIER | 47 48 | COMPONENT MANUFACTURER | 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The main stack flow transmitters failed due to the blades of the flow transmitting

1 1 | turbines becoming dirty preventing their rotation. These transmitters are located

1 2 | inside the main stack in the direct flow stream of both Unit I and II Offgas systems.

1 3 | The dirt was believed to be transported through this air flow. The transmitters were

1 4 | cleaned and returned to service.

7 8 9

1 5 | E | 28 | 0 | 9 | 9 | 29 | NA | 30 | A | 31 | Operator Observation

8 9 | FACILITY STATUS | 10 11 | % POWER | 12 13 | OTHER STATUS | 33 34 | METHOD OF DISCOVERY | 35 36 | DISCOVERY DESCRIPTION | 37 38

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36 | LOCATION OF RELEASE | 37 38

8 9 | RELEASED OR RELEASE | 10 11 | AMOUNT OF ACTIVITY | 12 13 | PERSONNEL EXPOSURES | 39 40

1 7 | 0 | 0 | 0 | 3 | Z | 40 | NA | 41

8 9 | NUMBER | 10 11 | TYPE | 12 13 | DESCRIPTION | 39 40

1 8 | 0 | 0 | 0 | 40 | NA | 41

8 9 | PERSONNEL INJURIES | 10 11 | NUMBER | 12 13 | DESCRIPTION | 41 42

1 9 | Z | 42 | NA | 43

8 9 | LOSS OF OR DAMAGE TO FACILITY | 10 11 | TYPE | 12 13 | DESCRIPTION | 41 42

2 0 | N | 44 | NA | 45

8 9 | PUBLICITY | 10 11 | ISSUED | 12 13 | DESCRIPTION | 45 46

7 8 9

7910240 476

1205 041

NRC USE ONLY

68 69

NAME OF PREPARER R. T. Nix

PHONE 912-367-7781