

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 FLCRP3 0000000000000000 41111 4 5
LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 32

01 L 050000302 102279 3 1021979 9
REPORT SOURCE 30 31 SYSTEM NUMBER 34 35 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 At 1510, as a result of a verification of computer analysis, it was reported
03 that fifty-one (51) additional seismic restraints had a safety factor of less
04 than four (4). This created an event reportable under Technical Specification
05 6.9.1.8.1. Redundancy NA. No effect upon the plant or general public. This
06 is the fourth occurrence of this type reported. Reference LER 79-061/01T-0,
07 79-087/01T-0, 79-087/01T-1.

08

09 Z Z B A SUIPDIRT X Z
SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP SUBCODE 14 VALVE SUBCODE 15

17 7 9 0 8 7 0 1 T 2
LER NO REPORT NUMBER 17 18 EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 27 28 REPORT TYPE 30 REVISION NO. 32

18 Z Z Z 0 0 0 0 Y N A P
ACTION TAKEN 23 FUTURE ACTION 24 EFFECT ON PLANT 25 SHUTDOWN METHOD 26 HOURS 27 ATTACHMENT SUBMITTED 30 NRC-4 FORM SUB. 31 PRIME COMP. SUPPLIER 32 COMPONENT MANUFACTURER 33

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 37

10 The cause of this event is attributed to inadequate design. Modification
11 79-6-86G has been initiated to redesign and repair the affected seismic
12 restraints.
13
14

15 E 1 0 0 NA D Notification from A/E
FACILITY STATUS 15 16 POWER 17 18 OTHER STATUS 19 20 METHOD OF DISCOVERY 21 22 DISCOVERY DESCRIPTION 23 24

16 Z Z NA NA
ACTIVITY CONTENT 25 26 RELEASED OF RELEASE 27 28 AMOUNT OF ACTIVITY 29 30 LOCATION OF RELEASE 31 32

17 0 0 0 Z NA
PERSONNEL EXPOSURES 33 34 NUMBER 35 36 TYPE 37 38 DESCRIPTION 39 40

18 0 0 0 NA
PERSONNEL INJURIES 41 42 NUMBER 43 44 DESCRIPTION 45 46

19 Z NA
LOSS OF OR DAMAGE TO FACILITY 47 48 TYPE 49 50 DESCRIPTION 51 52

20 N NA
PUBLICATION 53 54 DESCRIPTION 55 56

21 NA 7911060 348 J. Cooper, Jr. (904) 795-6486
NAME OF PREPARER 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82

NRC USE ONLY

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

1272 329

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-087/01T-2

Facility: Crystal River Unit #3

Report Date: 29 October 1979

Occurrence Date: 22 October 1979

Identification of Occurrence:

Inadequate design of seismic restraints reportable under Technical Specification 6.9.1.8.1.

Conditions Prior to Occurrence:

Mode 1 power operation (100%)

Description of Occurrence:

At 1510, as a result of a verification of computer analysis of seismic restraints, it was discovered that fifty-one (51) restraints have a safety factor less than four (4). Of those, four (4) restraints have a safety factor less than two (2), (SWR-490, SWR-517, SWR-521, and SFR-25). A modification has been initiated to redesign and repair the affected seismic restraints. Repairs to those restraints with a safety factor less than two (2) have been expedited. Repairs to the remaining restraints with safety factors between two (2) and four (4) are scheduled and are being worked on a priority basis.

Designation of Apparent Cause:

The cause of this event is attributed to inadequate design.

Analysis of Occurrence:

No effect upon the plant or general public.

Corrective Action:

Modification 79-6-86G has been initiated to redesign and repair the affected seismic restraints to achieve a safety factor greater than four (4) for each restraint. No further corrective action required.

Failure Data:

This is the fourth occurrence of this type reported. Reference LER 79-061/01T-0, 79-087/01T-0, and 79-087/01T-1.

/rc

1272 330