

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 2 | During steady-state power operation, the seismic bracing for cells 18 and 31 in
0 3 | the 201B battery was removed to allow for replacement of these cells. This
0 4 | resulted in the battery being declared inoperable in accordance with Section
0 5 | 3.8.2.3.b of the Technical Specifications. The cells were replaced, the seismic
0 6 | bracing reinstalled and the battery declared operable within approximately 3 hours.
0 7 |

1 0 | The cells had to be replaced as a result of a reduction in individual cell voltages
1 1 | although the cells were still operable. This condition was the subject of an informa-
1 2 | tional letter to the Office of Inspection and Enforcement on 2/20/79. Both the
1 3 | 201A and 201B batteries will be replaced as soon as new cells are available. This
1 4 | is expected to occur in the next several weeks.

7 8 9
FACILITY STATUS 1 5 [E] (28) 1 0 0 (29) NA (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION (32) Surveillance Testing
7 8 9 10 11 12 13 14 15 16
ACTIVITY CONTENT RELEASED OF RELEASE 1 6 [Z] (33) [Z] (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)
7 8 9 10 11 12 13 14 15 16
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (37) [Z] (38) NA
7 8 9 10 11 12 13 14 15 16
PERSONNEL INJURIES NUMBER DESCRIPTION (40) [Z] (41) NA
7 8 9 10 11 12 13 14 15 16
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (42) [Z] (43) NA
7 8 9 10 11 12 13 14 15 16
PUBLICITY ISSUED DESCRIPTION (44) [H] (45) NA
7 8 9 10 11 12 13 14 15 16
7 909100 3/8 NBC USE ONLY

POOR ORIGINAL

7909100 3/8

NRC USE ONLY

203-447-1791, EXT 544