


### LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

G	A	E	I	H	1	(2)	0	0	0	0	0	0	0	0	0	0	0	(3)	4	1	1	1	1	(4)			(5)	
LICENSEE CODE						LICENSE NUMBER														LICENSE TYPE							CAT	SG

REPORT SOURCE L 6 0 5 0 0 0 1 3 2 1 7 0 1 8 2 3 7 9 8 0 8 3 1 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 89

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While shutdown for refueling and performing hanger surveillance in response to IE Bul-

0 3 letin 79-14, it was discovered that a section of piping in the plant instrument air

0 4 system (P52) was not seismically supported per the original design. Further analysis

0 5 by the architect-engineer has revealed that since the controlling load for the support

0 6 was for seismic concerns only and since no seismic event has occurred, the piping was

0 7 not degraded. This is a repetitive occurrence. See LER 50-366/1978-02.

0 8		E 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
0 9		B		P 9	A 10	B 11	C 12	S U P P O R T 14				A 15	Z 16				
17		LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
7 9		7 9		0 6 5		0 1 1		T		0							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		APPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
X 33	18 34	Z 35	19 36	Z 37	20 38	Z 39	21 40	0 0 0 0 41	22 42	N 43	23 44	N 45	24 46	A 47	25 48	B 49	1 3 0 26 50
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																	

10 During initial installation of the piping and its associated hangers, the aforementioned-

11 ed hanger was inadvertently left off. The problem was corrected by installing a pipe

12 hanger as called for by original design. DADD

FACILITY STATUS				% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	11	28	0	0	0	29	N/A	C	31	During performance of 1E Bulletin 79-14	

ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	Z	(33)	Z	(34)	N/A	N/A

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	(37)	2	(38)	N/A		

PERSONNEL INJURIES				DESCRIPTION (41)	936338
1	2	3	4		
0	0	0	(40)	N/A	

7		9		11		12			
TYPE		LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION		(43)			
1	9	Z	(42)	N/A		7909110491			

7		8	9	10										
PUBLICITY					NRC USE ONLY									
ISSUED: DESCRIPTION (45)														
2	0	1	1	(44)	N/A									

## Narrative Report

On 8-23-79, with the Unit 1 Reactor shutdown for the refueling/maintenance outage, it was discovered while performing hanger surveillance in response to IE Bulletin 79-14 that a section of piping in the plant instrument air system (P52) was not seismically supported per the original design. Upon discovery of the installation error, the problem was corrected by installing a pipe hanger as called for by original design. This event had no impact on Unit 2 since the hanger surveillance has been previously completed, and any problems of a similar nature were corrected at that time. Further analysis by Bechtel has revealed that since the controlling load for the support was for seismic concerns only and since no seismic event has occurred, the piping was not degraded due to the support's absence.

POOR  
ORIGINAL

336339