

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 A L B R F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 7 8 9 14 15 25 26 30 37 CAT 38

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 2 5 9 7 0 8 2 3 7 9 8 0 9 0 6 7 9 9
 7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With unit in normal operation at 95% power, inspections were made in accordance with
 03 IE Bulletin 79-14. During this inspection it was found that restraints on certain CSSC
 04 systems were inoperable in that their configuration did not conform to the design
 05 specifications. There were no resulting significant occurrences, no previous similar
 06 events and no danger to health or safety of the public. This event was reported under
 07 T. S. 6.7.2.a.9.

08
 09
 10
 11
 12
 13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 63
 64
 65
 66
 67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (21)

10 Pipe vibration and/or improper installation during construction caused the inoperability.
 11 Similar restraints in units 1, 2 and 3 are being inspected and a followup report
 12 will be issued.

13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 63
 64
 65
 66
 67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100

100
 101
 102
 103
 104
 105
 106
 107
 108
 109
 110
 111
 112
 113
 114
 115
 116
 117
 118
 119
 120
 121
 122
 123
 124
 125
 126
 127
 128
 129
 130
 131
 132
 133
 134
 135
 136
 137
 138
 139
 140
 141
 142
 143
 144
 145
 146
 147
 148
 149
 150
 151
 152
 153
 154
 155
 156
 157
 158
 159
 160
 161
 162
 163
 164
 165
 166
 167
 168
 169
 170
 171
 172
 173
 174
 175
 176
 177
 178
 179
 180
 181
 182
 183
 184
 185
 186
 187
 188
 189
 190
 191
 192
 193
 194
 195
 196
 197
 198
 199
 200

201
 202
 203
 204
 205
 206
 207
 208
 209
 210
 211
 212
 213
 214
 215
 216
 217
 218
 219
 220
 221
 222
 223
 224
 225
 226
 227
 228
 229
 230
 231
 232
 233
 234
 235
 236
 237
 238
 239
 240
 241
 242
 243
 244
 245
 246
 247
 248
 249
 250
 251
 252
 253
 254
 255
 256
 257
 258
 259
 260
 261
 262
 263
 264
 265
 266
 267
 268
 269
 270
 271
 272
 273
 274
 275
 276
 277
 278
 279
 280
 281
 282
 283
 284
 285
 286
 287
 288
 289
 290
 291
 292
 293
 294
 295
 296
 297
 298
 299
 300

LER SUPPLEMENTAL INFORMATION

BFRO-60- 259 / 7918 Technical Specification Involved NA

Reported Under Technical Specification 6.7.2.a.9

Date of Occurrence 8/23/79 Time of Occurrence 3:45 p.m. Unit 1

Identification and Description of Occurrence: During inspections in accordance with IE Bulletin 79-14, PHRSW restraint R-8 was found to be inoperable in that of the four bolts required, the nuts on two through-bolts had fallen off and two through-bolts were missing.

Conditions Prior to Occurrence:

Unit 1 at 1045 MWe.
Unit 2 at 1095 MWe.
Unit 3 at 0 MWe - Maintenance Outage

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Pipe vibration and/or improper installation during construction apparently caused the two nuts to loosen and fall off. The missing through-bolts were apparently not installed during construction.

Analysis of Occurrence:

NA

POOR
ORIGINAL

Corrective Action:


Restraint R-8 has been repaired to design specifications. EN DES performed an evaluation and supplied a list of 41 similar restraints in units 1, 2 and 3 to be inspected. Of these, 31 have been inspected and of those inspected R-5, R-18, R-19, and R-22 on the PHRSW system. required repair work. A followup report will be issued at a later date.

Failure Data:

NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision:



949316