



Public Service Company of Colorado

16805 Weld County Road 19 1/2, Platteville, Colorado 80651

October 10, 1979
Fort St. Vrain
Unit No. 1
P-79230

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

REF: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/79-36/03-L-0, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/79-36/03-L-0.

Very truly yours,

Don Warembourg
Don Warembourg
Manager, Nuclear Production

DW/alk

cc: Director, MIPC

1154 139

Doc 5/11

7910160

409

S

REPORT DATE: October 10, 1979

REPORTABLE OCCURRENCE 79-36

OCCURRENCE DATE: September 10, 1979

ISSUE 0

Page 1 of 3

FORT ST. VRAIN NUCLEAR GENERATING STATION
PUBLIC SERVICE COMPANY OF COLORADO
P. O. BOX 361
PLATTEVILLE, COLORADO 80651

REPORT NO. 50-267/79-36/03-L-0

Final

IDENTIFICATION OF
OCCURRENCE:

On September 10, 1979, with the reactor in a shutdown condition, engineering personnel observed that cold reheat snubber CRS-262 was inoperable.

Since the reactor had been operated at power during the surveillance interval, this constitutes operation in a degraded mode of LCO 4.3.10, and is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)2.

EVENT
DESCRIPTION:

On September 10, 1979, with the reactor in a shutdown condition, engineering personnel observed that the pin at the piston rod eye of cold reheat snubber CRS-262 was missing. See details of Figure 1.

Because this pin was missing, the snubber was not properly attached to the pipe, and was therefore inoperable. This snubber had been verified operable per approved surveillance procedure during the refueling shutdown.

CAUSE
DESCRIPTION:

Prior to startup following the first refueling, this snubber was operable. There appears to be no cause for this missing pin traceable to plant operation.

CORRECTIVE
ACTION:

A new pin was fabricated and installed and the snubber was returned to service. The present surveillance interval is 12 months \pm 25%. No change is required as a result of this occurrence.

No further corrective action is anticipated or required.

1154 140

figs. 200, 201

POOR ORIGINAL




FIGURE 1

1154 141

Prepared by: Cathy C. Collard
Cathy C. Collard
Technical Services Technician

Reviewed by: S. W. Gahm
S. W. Gahm
Technical Services Supervisor

Reviewed by: Frank M. Mathie
Frank M. Mathie
Operations Manager

Approved by: Don Warembourg
Don Warembourg
Manager, Nuclear Production

1154 142