

## LICENSEE EVENT REPORT

LER 79-24/3L

CONTROL BLOCK: 

1	2	3	4	5	6
---	---	---	---	---	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	T	V	Y	S	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0	1	L	6	0	5	0	0	0	2	7	1	7	0	9	2	0	7	9	8	1	0	1	8	7	9	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2																										
0	3	See attached sheet																									
0	4																										
0	5																										
0	6																										
0	7																										
0	8																										

0	9																										
---	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 19 VALVE SUBCODE 20

EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 26 OCCURRENCE CODE 28 29 REPORT TYPE 30 REVISION NO. 32

LER RO REPORT NUMBER 17 ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 40 ATTACHMENT SUBMITTED 41 43 NPRD-4 FORM SUB. 42 PRIME COMP. SUPPLIER 43 COMPONENT MANUFACTURER 44 47

18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0																										
1	1	See attached sheet																									
1	2																										
1	3																										
1	4																										

1	5	Z	28	0	8	8	29	NA	30	A	31	Operator Observation	32												
---	---	---	----	---	---	---	----	----	----	---	----	----------------------	----	--	--	--	--	--	--	--	--	--	--	--	--

FACILITY STATUS 7 8 % POWER 10 11 OTHER STATUS 12 13 METHOD OF DISCOVERY 44 45 DISCOVERY DESCRIPTION 46 47

1	6	Z	33	Z	34	NA	35	NA	36												
---	---	---	----	---	----	----	----	----	----	--	--	--	--	--	--	--	--	--	--	--	--

ACTIVITY CONTENT 7 8 RELEASED OF RELEASE 10 11 AMOUNT OF ACTIVITY 44 45 LOCATION OF RELEASE 46 47

1	7	0	0	0	37	Z	38	NA	39												
---	---	---	---	---	----	---	----	----	----	--	--	--	--	--	--	--	--	--	--	--	--

PERSONNEL EXPOSURES NUMBER 7 8 TYPE 10 11 DESCRIPTION 12 13

1	8	0	0	0	40	NA	41												
---	---	---	---	---	----	----	----	--	--	--	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES NUMBER 7 8 DESCRIPTION 10 11

1	9	Z	42	NA	43												
---	---	---	----	----	----	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OF OR DAMAGE TO FACILITY TYPE 7 8 DESCRIPTION 10 11

2	0	Z	44	NA	45												
---	---	---	----	----	----	--	--	--	--	--	--	--	--	--	--	--	--

PUBLICITY ISSUED 7 8 DESCRIPTION 10 11

NAME OF PREPARER W. F. Conway

PHONE: 802-257-7711

7910220243

NRC USE ONLY

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During steady state operation, Control Room personnel observed an abrupt change in indicated torus water level on Control Room Indicators LI-16-19-46A/B. Channel A increased from 1.15' to 4.54' while Channel B increased from 1.15' to 6.13'. Additionally, the HPCI suction valves shifted line-up from the condensate storage tank to the torus.

Upon investigation, it was revealed that contractor personnel, while erecting staging, dislodged a fitting on the torus level transmitters thereby draining the leg and causing the erroneous readings. Technical Specification 3.2.G requires this post-accident instrumentation be operable during reactor operation. At no time was the torus water inventory out of specification. Since this indication was restored within the limiting 6 hours of Tech. Spec. Table 3.2.6, the plant continued power operation. The potential based on the above consequences to the health and safety of the public were minimal.

CORRECTIVE ACTION TAKEN

The fitting was repaired, the reference leg refilled, and the instruments returned to operation. It has been further reemphasized to all contract personnel of the necessity to proceed with caution during all phases of their work activities.