

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

REPORT  
SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

Please See Attachment

0	2	Please See Attachment
0	3	
0	4	
0	5	
0	6	
0	7	
0	8	

SYSTEM CODE S F (11)		CAUSE CODE B (12)		CAUSE SUBCODE A (13)		COMPONENT CODE S U P P O R T (14)		COMP. SUBCODE B (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 7 9 (17)		SEQUENTIAL REPORT NO. 0 7 1 (18)		OCCURRENCE CODE 0 1 (19)		REPORT TYPE T (20)		REVISION NO. 0 (21)			
ACTION TAKEN F (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED Y (23)	
NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER A (25)		COMPONENT MANUFACTURER S 4 2 0 (26)							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Please See Attachment

1	0	Please See Attachment
1	1	
1	2	
1	3	
1	4	

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	9	0	9	6	NA	D	Architect Engineer						
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	6	Z	Z	NA										
PERSONNEL EXPOSURES			PERSONNEL INJURIES			LOSS OF OR DAMAGE TO FACILITY			PUBLICITY					
1	7	0	0	0	0	0	0	Z						
NUMBER			TYPE			DESCRIPTION			NRC USE ONLY					
0	0	0	Z	NA										
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION			TYPE			DESCRIPTION					
0	0	0	NA											
NUMBER			DESCRIPTION											

NAME OF PREPARER W. Verne Childs

PHONE: 315-342-3840

POWER AUTHORITY OF THE STATE OF NEW YORK  
JAMES A. FLETCHER NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 79-071-01T-0

Page 1 of 1

During normal operation, as the result of the Pipe Stress Reanalysis being conducted by the Architect Engineer, the plant staff was notified that pipe support H15-124 on the Emergency Service Water return piping to the lake was inoperable. As set forth in the August 14, 1979 letter lifting the Show Cause Order of March 13, 1979, further analysis was performed which showed this piping to become inoperable without this support. Since this portion of the Emergency Service Water System does not adversely effect the ability of the system to perform its intended safety function the seven (7) day time frame for modifications described in the August 14, 1979 letter applies.

Modification of H15-124 was completed within the seven (7) day time frame. Since the affected piping was downstream of components cooled by Emergency Service Water, the support would not, in its original design condition, have affected the plant's ability to achieve cold shutdown. Therefore, the event did not represent any significant hazard to the public health and safety.

1149 304