

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L C R P 3 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 - - 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT
01 REPORT SOURCE L 3 0 5 0 - 0 3 0 2 7 1 0 2 8 7 9 3 1 1 2 0 7 9 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
COCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 0400 during the performance of Daily Operating Surveillance SP-300, it was
03 reported that the remote shutdown indicator for "B" decay heat cooler outlet
04 temperature DH-40-TI was inoperable. This created an event contrary to Technical
05 Specification 3.3.3.5. No effect upon the plant or general public. This is
06 the second occurrence reported for DH-40-TI. Reference LER 79-095.
07
08
09

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
09 C F 11 E 12 E 13 I N S T R U 14 X 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

LER NO. REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM 386 PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event is attributed to a loose precision resistor assembly.
11 The resistor bridge assembly was tightened and DH-40-TI indication returned to
12 within tolerance. DH-40-TI was returned to service at 0900 on 2 November 1979.
13 REI 79-10-11 has been initiated to evaluate decay heat remote shutdown indication
14
15

FACILITY STATUS POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
15 E 16 1 0 0 17 NA 18 R 19 Operator observation
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

ACTIVITY CONTENT AMOUNT OF ACTIVITY LOCATION OF RELEASE
16 Z 17 Z 18 NA 19 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PERSONNEL EXPOSURES
17 0 0 0 18 Z 19 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PERSONNEL INJURIES
18 0 0 0 19 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

LOSS OF OR DAMAGE TO FACILITY
19 Z 20 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PLANT STATUS DESCRIPTION
20 N 21 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

7911300 522

Name of preparer: KFL K. F. Lancaster PHONE: (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

1444 077

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-104/03L-0

Facility: Crystal River Unit #3

Report Date: 20 November 1979

Occurrence Date: 28 October 1979

Identification of Occurrence:

Remote shutdown indicator for "B" decay heat cooler outlet temperature DH-40-TI inoperable, contrary to Technical Specification 3.3.3.5.

Conditions Prior to Occurrence:

Mode 1 power operation (100%).

Description of Occurrence:

At 0400 during the performance of Daily Operating Surveillance SP-300 it was reported that the remote shutdown indicator for "B" decay heat cooler outlet temperature, DH-40-TI was inoperable. It was discovered that DH-40-TI (103°F) was inconsistent with redundant Control Room indicator DH-2-TI-2 (95°F) and "B" decay heat pump suction indicator DH-6-TI-2 (80°F). Maintenance restored operability and DH-40-TI was returned to service at 0900 on 2 November 1979.

Designation of Apparent Cause:

The cause of this event is attributed to a loose precision resistor bridge assembly. The resistor bridge assembly was tightened and DH-40-TI was returned to service.

Analysis of Occurrence:

No effect upon the plant or general public.

Corrective Action:

REI 79-10-11 has been initiated to evaluate decay heat remote shutdown temperature indication. Further corrective action will be based upon the results of this evaluation and submitted as a supplement to this report.

Failure Data:

This is the second occurrence reported for DH-40-TI. Reference LER 79-095.

/rc

1446 078